

Recall Detail

Ref No	10000925
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	E 63 S, S 63, AMG GT 63 S and G 63 / 213, 222, 290, and 463
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hunghom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Oil feed line to exhaust gas turbocharger (0993102)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The elastomer material of the oil feed line to the exhaust gas turbocharger in affected vehicles may not correspond to the specification. This may lead to isolated leakages of the oil feed line due to thermal load while the vehicle is in operation.</p> <p>In this case, it cannot be ruled out that leaking oil may come into contact with hot component parts. This may result in a fire risk.</p>
Remedial Action	Replace the oil feed line to the exhaust gas turbocharger in affected vehicles as a precautionary measure.
Build Dates	12/06/2018 - 11/02/2019
Launch Date	20/02/2020
Tentative Date of Recall Completion	31/12/2020

1

WDB4632761X302417

3

WDB4632762X300658

2

WDB4632761X302478

4

WDB4632762X301013

5	WDB4632762X302531
6	WDB4632762X302540
7	WDB4632762X302571
8	WDB4632762X302577
9	WDB4632762X302597
10	WDB4632762X302676
11	WDB4632762X302794
12	WDB4632762X302924
13	WDB4632762X303030
14	WDB4632762X303103
15	WDB4632762X303196
16	WDB4632762X303207
17	WDB4632762X303286
18	WDB4632762X303386
19	WDB4632762X303450
20	WDB4632762X303487
21	WDB4632762X303543
22	WDB4632762X303626
23	WDB4632762X303644
24	WDB4632762X303906
25	WDB4632762X304037
26	WDB4632762X304260
27	WDB4632762X304754
28	WDB4632762X304882
29	WDB4632762X305001
30	WDB4632762X305085
31	WDB4632762X305233
32	WDB4632762X305236
33	WDB4632762X305461
34	WDB4632762X305488
35	WDB4632762X305497
36	WDB4632762X307051
37	WDB4632762X307135
38	WDB4632762X307839
39	WDD2130892A501850
40	WDD2130892A503928
41	WDD2130892A505231
42	WDD2130892A505408
43	WDD2130892A505531
44	WDD2130892A505592

45	WDD2130892A505745
46	WDD2130892A506002
47	WDD2130892A509752
48	WDD2130892A512319
49	WDD2130892A512927
50	WDD2130892A519915
51	WDD2130892A522235
52	WDD2130892A524154
53	WDD2130892A524466
54	WDD2130892A524620
55	WDD2130892A525301
56	WDD2130892A538209
57	WDD2130892A549035
58	WDD2130892A549209
59	WDD2130892A549284
60	WDD2130892A553389
61	WDD2221872A425103
62	WDD2221872A427928
63	WDD2221872A432405
64	WDD2221872A449699
65	WDD2906892A001219
66	WDD2906892A001230