

Recall Detail

Ref No	10000929
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Bentayga
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
Subject	Bentayga – Seven Seat – Third Row Safety Belt
Progress	In process
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The third-row seat belt pillar loop upper anchorages may not fulfil the legal load requirements. Therefore, in the event of an impact accident, there is a risk that the third-row rear seat belt pillar loops may become detached from the body structure.
Remedial Action	The D-post seat belt pillar loop upper anchorages socket head collared bolt & clips will be replaced.
Build Dates	Sep 2016 - Jan 2020
Launch Date	24 Mar 2020
Tentative Date of Recall Completion	

VIN
SJA AF34V2JC017197
SJA AF34V2JC017877
SJA AF34V5JC018229
SJA AF34V5JC018361
SJA AF34V9JC020694
SJA AF34V6JC021334
SJA AL34V8KC024214
SJA AF34V7KC025507
SJA AL34V9KC026733
SJA AB34VXLC029340
SJA AB34V4LC030760
SJA AF34V5JC017954
SJA AF34VXJC020526
SJA AF34V1JC017434
SJA AF34V6JC017994