

Recall Detail	
Ref No	10000936
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	M6 (F06)
Dealer (phone no)	31936688
Subject	Reworking the high-mounted 3rd brake light
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	The high-mounted brake light is mounted on the standard carbon fibre-reinforced plastic (CFRP) roof using six screw connections. Due to the setting properties of CFRP under pressure and heat, the screw connections lose their preload force and rattle under dynamic stimulation while driving. In rare cases, the brake light can be completely detached.
Remedial Action	Remount the high-mounted brake light in the centre area.
Build Dates	02-08-2013 to 05-03-2015
Launch Date	27-02-2020
Tentative Date of Recall Completion	28-02-2021

1	WBS6C92000D879245
2	WBS6C92010DV74370
3	WBS6C92020DV74362
4	WBS6C92040DV74203
5	WBS6C92040DV74217
6	WBS6C92040DV74248
7	WBS6C92050DV74212
8	WBS6C92050DV74257
9	WBS6C92070DV74406
10	WBS6C92080DV74253
11	WBS6C92080DV74432
12	WBS6C92080DV74463
13	WBS6C92090DV74228
14	WBS6C92090DV74357
15	WBS6C92090DV74360
16	WBS6C920X0DV74254
17	WBS6C920X0DV74397
18	WBS6E92040GS38706