

## Recall Detail

<b>Ref No</b>	<b>10000944</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	G-Class / 463
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Rear door child safety lock symbol (7390003)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The lock symbol embossed on the rear doors for the child safety lock in affected vehicles may show the locking status incorrectly.</p> <p>In this case, the incorrectly embossed symbol may result in a misinterpretation of the locking status of the child safety lock. It may thus be possible to open the rear doors from the inside in spite of supposed locking. Vice versa, it may not be possible to open the rear doors from the inside in spite of supposed unlocking.</p> <p>This could result in a risk of injury and/or an increased risk of injury for the occupants in the rear.</p>
<b>Remedial Action</b>	As a precautionary measure in affected vehicles affix a correct label over the incorrectly embossed lock symbol in the rear doors.
<b>Build Dates</b>	07/09/2018 - 12/09/2019
<b>Launch Date</b>	29/05/2020
<b>Tentative Date of Recall Completion</b>	31/12/2020

1	WDB4632761X302417
2	WDB4632761X302478
3	WDB4632761X325796
4	WDB4632761X330838
5	WDB4632762X300658
6	WDB4632762X301013
7	WDB4632762X302531
8	WDB4632762X302540
9	WDB4632762X302571
10	WDB4632762X302577
11	WDB4632762X302597
12	WDB4632762X302676
13	WDB4632762X302794
14	WDB4632762X302924
15	WDB4632762X303030
16	WDB4632762X303103
17	WDB4632762X303196
18	WDB4632762X303207
19	WDB4632762X303286
20	WDB4632762X303386
21	WDB4632762X303450
22	WDB4632762X303487
23	WDB4632762X303543
24	WDB4632762X303626
25	WDB4632762X303644
26	WDB4632762X303906
27	WDB4632762X304037
28	WDB4632762X304260
29	WDB4632762X304487
30	WDB4632762X304581
31	WDB4632762X304587
32	WDB4632762X304754
33	WDB4632762X304882
34	WDB4632762X304986
35	WDB4632762X305001
36	WDB4632762X305085
37	WDB4632762X305233
38	WDB4632762X305236
39	WDB4632762X305461
40	WDB4632762X305488

41	WDB4632762X305497
42	WDB4632762X307051
43	WDB4632762X307135
44	WDB4632762X307839
45	WDB4632762X308383
46	WDB4632762X308539
47	WDB4632762X308691
48	WDB4632762X308753
49	WDB4632762X308788
50	WDB4632762X308811
51	WDB4632762X308875
52	WDB4632762X309029
53	WDB4632762X312277
54	WDB4632762X313695
55	WDB4632762X313900
56	WDB4632762X313929
57	WDB4632762X314092
58	WDB4632762X314263
59	WDB4632762X314267
60	WDB4632762X315216
61	WDB4632762X315238
62	WDB4632762X316540
63	WDB4632762X316858
64	WDB4632762X317197
65	WDB4632762X317345
66	WDB4632762X317859
67	WDB4632762X318582
68	WDB4632762X320180
69	WDB4632762X320230
70	WDB4632762X320329
71	WDB4632762X320509
72	WDB4632762X320874
73	WDB4632762X321011
74	WDB4632762X321237
75	WDB4632762X321450
76	WDB4632762X321993
77	WDB4632762X322637
78	WDB4632762X323139
79	WDB4632762X323196
80	WDB4632762X323357

81	WDB4632762X323409
82	WDB4632762X323779
83	WDB4632762X323793
84	WDB4632762X323828
85	WDB4632762X324083
86	WDB4632762X324245
87	WDB4632762X325905
88	WDB4632762X325967
89	WDB4632762X326018
90	WDB4632762X326092
91	WDB4632762X326104
92	WDB4632762X326156
93	WDB4632762X326347
94	WDB4632762X327440
95	WDB4632762X327679
96	WDB4632762X327763
97	WDB4632762X327930
98	WDB4632762X329218
99	WDB4632762X329246
100	WDB4632762X329924
101	WDB4632762X329974
102	WDB4632762X329999
103	WDB4632762X330015
104	WDB4632762X330025
105	WDB4632762X330076
106	WDB4632762X330087
107	WDB4632762X330257
108	WDB4632762X330282
109	WDB4632762X330304
110	WDB4632762X330395
111	WDB4632762X330435
112	WDB4632762X330526
113	WDB4632762X330535
114	WDB4632762X330567
115	WDB4632762X330583
116	WDB4632762X330661
117	WDB4632762X330774
118	WDB4632762X330945
119	WDB4632762X330952
120	WDB4632762X330973

121	WDB4632762X331026
122	WDB4632762X331042
123	WDB4632762X331364
124	WDB4632762X332150
125	WDB4632762X332165
126	WDB4632762X332218
127	WDB4632762X332509
128	WDB4632762X332603
129	WDB4632762X332780
130	WDB4632762X333016
131	WDB4632762X333034
132	WDB4632762X333106
133	WDB4632762X333150
134	WDB4632762X333198
135	WDB4632762X333210
136	WDB4632762X333386
137	WDB4632762X333407
138	WDB4632762X333426
139	WDB4632762X333447
140	WDB4632762X333472
141	WDB4632762X333503
142	WDB4632762X333572
143	WDB4632762X333695
144	WDB4632762X333746
145	WDB4632762X333789
146	WDB4632762X333875
147	WDB4632762X333924
148	WDB4632762X333995
149	WDC4632601X317793