

Recall Detail

Ref No	10000952
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	G-Class / 463
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Differential lock system (3395003)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The control unit of the differential locking module on affected vehicles might not meet the specification. The electrical contact of a specific resistor might be impaired due to sulfur fumes originating from the axle oil. If the resistor is impaired, the electrical currents calculated with this resistor would have a higher value than in fact exists.</p> <p>In consequence, the communication between the control unit and the locking actuator will be shut down. In this case, the differential locking status could not be reliably determined.</p> <p>According to the specified system strategy for locked differentials, both ESP and ABS systems would be deactivated. This could increase the risk of a crash under certain operating conditions.</p>
Remedial Action	Check the differential locking modules on affected vehicles as a precautionary measure, and replace them if necessary.
Build Dates	07/09/2018 - 30/09/2019
Launch Date	07/07/2020
Tentative Date of Recall Completion	31/12/2020

1	WDB4632761X302417
2	WDB4632761X302478
3	WDB4632761X325796
4	WDB4632761X330838
5	WDB4632762X300658
6	WDB4632762X301013
7	WDB4632762X302531
8	WDB4632762X302540
9	WDB4632762X302571
10	WDB4632762X302577
11	WDB4632762X302597
12	WDB4632762X302676
13	WDB4632762X302794
14	WDB4632762X302924
15	WDB4632762X303030
16	WDB4632762X303103
17	WDB4632762X303196
18	WDB4632762X303207
19	WDB4632762X303286
20	WDB4632762X303386
21	WDB4632762X303450
22	WDB4632762X303487
23	WDB4632762X303543
24	WDB4632762X303626
25	WDB4632762X303644
26	WDB4632762X303906
27	WDB4632762X304037
28	WDB4632762X304260
29	WDB4632762X304487
30	WDB4632762X304581
31	WDB4632762X304587
32	WDB4632762X304754
33	WDB4632762X304882
34	WDB4632762X304986
35	WDB4632762X305001
36	WDB4632762X305085
37	WDB4632762X305233
38	WDB4632762X305236

39	WDB4632762X305461
40	WDB4632762X305488
41	WDB4632762X305497
42	WDB4632762X307051
43	WDB4632762X307135
44	WDB4632762X307839
45	WDB4632762X308383
46	WDB4632762X308691
47	WDB4632762X308753
48	WDB4632762X308788
49	WDB4632762X308811
50	WDB4632762X308875
51	WDB4632762X309029
52	WDB4632762X312277
53	WDB4632762X313695
54	WDB4632762X313900
55	WDB4632762X313929
56	WDB4632762X314092
57	WDB4632762X314263
58	WDB4632762X314267
59	WDB4632762X315216
60	WDB4632762X315238
61	WDB4632762X316540
62	WDB4632762X316858
63	WDB4632762X317197
64	WDB4632762X317345
65	WDB4632762X317859
66	WDB4632762X318582
67	WDB4632762X320180
68	WDB4632762X320230
69	WDB4632762X320329
70	WDB4632762X320509
71	WDB4632762X320874
72	WDB4632762X321011
73	WDB4632762X321237
74	WDB4632762X321450
75	WDB4632762X321993
76	WDB4632762X322637

77	WDB4632762X323139
78	WDB4632762X323196
79	WDB4632762X323357
80	WDB4632762X323409
81	WDB4632762X323779
82	WDB4632762X323793
83	WDB4632762X323828
84	WDB4632762X324083
85	WDB4632762X324245
86	WDB4632762X325905
87	WDB4632762X325967
88	WDB4632762X326018
89	WDB4632762X326092
90	WDB4632762X326104
91	WDB4632762X326156
92	WDB4632762X326347
93	WDB4632762X327440
94	WDB4632762X327679
95	WDB4632762X327763
96	WDB4632762X327930
97	WDB4632762X329218
98	WDB4632762X329246
99	WDB4632762X329924
100	WDB4632762X329974
101	WDB4632762X329999
102	WDB4632762X330015
103	WDB4632762X330025
104	WDB4632762X330076
105	WDB4632762X330087
106	WDB4632762X330257
107	WDB4632762X330282
108	WDB4632762X330304
109	WDB4632762X330395
110	WDB4632762X330435
111	WDB4632762X330526
112	WDB4632762X330535
113	WDB4632762X330567
114	WDB4632762X330583
115	WDB4632762X330661
116	WDB4632762X330774

117	WDB4632762X330945
118	WDB4632762X330952
119	WDB4632762X330973
120	WDB4632762X331026
121	WDB4632762X331042
122	WDB4632762X331364
123	WDB4632762X332150
124	WDB4632762X332165
125	WDB4632762X332218
126	WDB4632762X332509
127	WDB4632762X332603
128	WDB4632762X332780
129	WDB4632762X333016
130	WDB4632762X333034
131	WDB4632762X333106
132	WDB4632762X333150
133	WDB4632762X333198
134	WDB4632762X333210
135	WDB4632762X333386
136	WDB4632762X333407
137	WDB4632762X333426
138	WDB4632762X333447
139	WDB4632762X333472
140	WDB4632762X333503
141	WDB4632762X333572
142	WDB4632762X333695
143	WDB4632762X333746
144	WDC4632601X317793