Recall Detail				
Ref No	10000953			
Manufacturer	Daimler AG			
Vehicle Class	Private car			
Model/Type	AMG GT S / 190			
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140			
	Yuen Long Service Centre: 2504 6140			
Subject	Idle speed too low after a cold start (5490316)			
Progress	Running			
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.			
Description of Defect, how it came to light, and possible consequences if ignored.	The control unit software of affected vehicles may not correspond to specifications. If the vehicle is shut off for more than 67 hours, this may cause the catalytic converter to be heated more slowly than is intended. As a result, it is possible that legal emissions requirements may not be complied with.			
Remedial Action	Update the control unit software on affected vehicles as a precautionary measure.			
Build Dates	16/04/2015 - 14/04/2016			
Launch Date	07/07/2020			
Tentative Date of Recall Completion	31/12/2020			

1	WDD1903782A002229	6	WDD1903782A003561
2	WDD1903782A003072	7	WDD1903782A003991
3	WDD1903782A003139	8	WDD1903782A004093
4	WDD1903782A003175	9	WDD1903782A004305
5	WDD1903782A003375	10	WDD1903782A004817

11	WDD1903782A004866
12	WDD1903782A005135
13	WDD1903782A005506
14	WDD1903782A005754
15	WDD1903782A008386
16	WDD1903782A009817