

Recall Detail

Ref No	10000954
Manufacturer	Honda
Vehicle Class	Private Car
Model/Type	CR-V RW2
Dealer (phone no)	22168183
Subject	Replace of Fuel Pump Kit
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Affected vehicles may be equipped with a fuel pump module manufactured with low density impellers. If the surface of the lower density impeller is exposed to production solvent drying for longer periods of time, higher levels of surface cracking may occur. These cracks may lead to excessive fuel absorption, resulting in impeller deformation. Over time, if an impeller deforms to a point that creates sufficient interference with the fuel pump body, the fuel pump becomes inoperative, which may cause illumination of the Malfunction Indicator Lamp in the instrument panel. Fuel pump inoperability could prevent an engine from starting or stall an engine while driving, increasing the risk of a crash.
Remedial Action	Replace of Fuel Pump Kit
Build Dates	2018
Launch Date	13 JUL 2020
Tentative Date of Recall Completion	13 JUL 2027

MRHRW2840JP030282
 MRHRW2840JP030283
 MRHRW2840JP030284
 MRHRW2840JP030285
 MRHRW2840JP030286
 MRHRW2840JP030287
 MRHRW2840JP030288
 MRHRW2840JP030289
 MRHRW2840JP030290
 MRHRW2840JP030291
 MRHRW2840JP030292
 MRHRW2840JP030293
 MRHRW2840JP030295
 MRHRW2840JP030296
 MRHRW2840JP030297

MRHRW2840JP030298
 MRHRW2840JP030299
 MRHRW2840JP030300
 MRHRW2840JP030301
 MRHRW2840JP030302
 MRHRW2840JP030303
 MRHRW2840JP030304
 MRHRW2840JP030305
 MRHRW2840JP030306
 MRHRW2840JP030307
 MRHRW2840JP030308
 MRHRW2840JP030309
 MRHRW2840JP030310
 MRHRW2840JP030312
 MRHRW2840JP030313

MRHRW2840JP030314
MRHRW2840JP030315
MRHRW2840JP030316
MRHRW2840JP030317
MRHRW2840JP030318
MRHRW2840JP030319
MRHRW2840JP030320
MRHRW2840JP030321
MRHRW2840JP030322
MRHRW2840JP030323
MRHRW2840JP030324
MRHRW2840JP030325
MRHRW2840JP030327
MRHRW2840JP030328
MRHRW2840JP030329
MRHRW2840JP030330
MRHRW2840JP030331
MRHRW2840JP030332
MRHRW2840JP030333
MRHRW2840JP030334
MRHRW2840JP030335
MRHRW2840JP030336
MRHRW2840JP030337
MRHRW2840JP030338
MRHRW2840JP030339
MRHRW2840JP030340
MRHRW2840JP030341
MRHRW2840JP030342
MRHRW2840JP030343
MRHRW2840JP030344
MRHRW2840JP030345
MRHRW2840JP030346
MRHRW2840JP030347
MRHRW2840JP030348
MRHRW2840JP030349
MRHRW2840JP030350
MRHRW2840JP030351
MRHRW2840JP030352
MRHRW2840JP030353

MRHRW2840JP030354
MRHRW2840JP030355
MRHRW2840JP030356