

## Recall Detail

<b>Ref No</b>	<b>10000955</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	CIVIC TYPE R FK8
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Replace of Fuel Pump Kit
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Affected vehicles may be equipped with a fuel pump module manufactured with low density impellers. If the surface of the lower density impeller is exposed to production solvent drying for longer periods of time, higher levels of surface cracking may occur. These cracks may lead to excessive fuel absorption, resulting in impeller deformation. Over time, if an impeller deforms to a point that creates sufficient interference with the fuel pump body, the fuel pump becomes inoperative, which may cause illumination of the Malfunction Indicator Lamp in the instrument panel. Fuel pump inoperability could prevent an engine from starting or stall an engine while driving, increasing the risk of a crash.
<b>Remedial Action</b>	Replace of Fuel Pump Kit
<b>Build Dates</b>	2018
<b>Launch Date</b>	13 JUL 2020
<b>Tentative Date of Recall Completion</b>	13 JUL 2027

SHHFK8730JU750106	SHHFK8730JU750122
SHHFK8730JU750108	SHHFK8730JU750123
SHHFK8730JU750109	SHHFK8730JU750124
SHHFK8730JU750110	SHHFK8730JU750125
SHHFK8730JU750111	SHHFK8730JU750126
SHHFK8730JU750112	SHHFK8730JU750127
SHHFK8730JU750113	SHHFK8730JU750128
SHHFK8730JU750114	SHHFK8730JU750129
SHHFK8730JU750115	SHHFK8730JU750130
SHHFK8730JU750116	SHHFK8730JU750131
SHHFK8730JU750117	SHHFK8730JU750132
SHHFK8730JU750118	SHHFK8730JU750133
SHHFK8730JU750119	SHHFK8730JU750134
SHHFK8730JU750120	SHHFK8730JU750135
SHHFK8730JU750121	SHHFK8730JU750136

SHHFK8730JU750137  
SHHFK8730JU750138  
SHHFK8730JU750139  
SHHFK8730JU750140  
SHHFK8730JU750141  
SHHFK8730JU750142  
SHHFK8730JU750143  
SHHFK8730JU750144  
SHHFK8730JU750145  
SHHFK8730JU750146  
SHHFK8730JU750147  
SHHFK8730JU750148  
SHHFK8730JU750149  
SHHFK8730JU750150  
SHHFK8730JU750151  
SHHFK8730JU750152  
SHHFK8730JU750153  
SHHFK8730JU750154  
SHHFK8730JU750155  
SHHFK8730JU750156  
SHHFK8730JU750157  
SHHFK8730JU750159  
SHHFK8730JU750160  
SHHFK8730JU750162