

## Recall Detail

<b>Ref No</b>	<b>10000961</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	V-Class / 447
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Check manufacturing date of propeller shaft and replace propeller shaft if necessary (4190166)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The propeller shaft may not have been properly fixed in place on the propeller shaft center support bearing on certain affected vehicles. If this should cause damage to the ball joint, it may result in excitation of the underbody caused by imbalance. In the worst case, this could affect the control unit, which could then interpret this as influences acting on the vehicle that usually occur only in the case of certain crash events during normal vehicle operation.</p> <p>If a mistakenly detected crash event were to cause restraint equipment such as front airbags to be triggered unintentionally, an elevated risk of injury and accident could arise.</p>
<b>Remedial Action</b>	Check the propeller shaft and replace it if necessary, as a precautionary measure.
<b>Build Dates</b>	04/01/2019 - 18/01/2019
<b>Launch Date</b>	10/07/2020
<b>Tentative Date of Recall Completion</b>	31/12/2020

1	WDF44781323560580
2	WDF44781323561308
3	WDF44781323562313
4	WDF44781323563251
5	WDF44781323564174
6	WDF44781323564269
7	WDF44781323565578
8	WDF44781323567140