

Recall Detail

Ref No	10000968
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	GLB / 247
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Rear spoiler (7792002)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The rear spoiler located above the tailgate of affected vehicles might have been manufactured outside specifications. The upper shell of the rear spoiler might not have been welded or welded incorrectly to the base part. In case of a missing welding, it cannot be ensured that the upper shell is sufficiently connected to the base part. Should the rear spoiler have been welded incorrectly, the weld could break in case of a collision of the rear spoiler with the vehicle roof when opening the tailgate of the vehicle.</p> <p>In both cases, it cannot be ruled out that parts of the rear spoiler might detach while driving. This would increase the risk of a crash or injury for other road users.</p>
Remedial Action	Check the rear spoiler on affected vehicles and perform any necessary corrections as a precautionary measure.
Build Dates	01/02/2020 - 05/03/2020
Launch Date	29/09/2020

**Tentative Date of
Recall Completion**

31/03/2021

1	W1N2476472W028312	38	W1N2476472W030927
2	W1N2476472W028401	39	W1N2476472W031004
3	W1N2476472W028454	40	W1N2476472W031051
4	W1N2476472W028666	41	W1N2476472W031073
5	W1N2476472W028921	42	W1N2476472W031078
6	W1N2476472W028925	43	W1N2476472W031143
7	W1N2476472W028927	44	W1N2476472W031207
8	W1N2476472W028935	45	W1N2476472W031213
9	W1N2476472W028954	46	W1N2476472W031226
10	W1N2476472W029053	47	W1N2476472W031248
11	W1N2476472W029128	48	W1N2476472W031282
12	W1N2476472W029207	49	W1N2476472W031358
13	W1N2476472W029215	50	W1N2476472W031393
14	W1N2476472W029355	51	W1N2476472W031460
15	W1N2476472W029381	52	W1N2476472W032479
16	W1N2476472W029404	53	W1N2476472W032620
17	W1N2476472W029531	54	W1N2476472W032653
18	W1N2476472W029541	55	W1N2476472W032711
19	W1N2476472W029603	56	W1N2476472W032753
20	W1N2476472W029618	57	W1N2476472W034956
21	W1N2476472W029683	58	W1N2476472W035015
22	W1N2476472W029723	59	W1N2476472W035036
23	W1N2476472W029726	60	W1N2476472W035049
24	W1N2476472W029749	61	W1N2476472W035160
25	W1N2476472W029756	62	W1N2476472W035204
26	W1N2476472W029816	63	W1N2476472W035321
27	W1N2476472W029943	64	W1N2476472W035332
28	W1N2476472W030013	65	W1N2476472W035378
29	W1N2476472W030098	66	W1N2476472W035403
30	W1N2476472W030230	67	W1N2476472W035412
31	W1N2476472W030260	68	W1N2476472W035484
32	W1N2476472W030314	69	W1N2476472W035488
33	W1N2476472W030335	70	W1N2476472W035496
34	W1N2476472W030433	71	W1N2476472W035499
35	W1N2476472W030562	72	W1N2476472W035513
36	W1N2476472W030572	73	W1N2476472W035518
37	W1N2476472W030646	74	W1N2476472W035536

75	W1N2476472W035578
76	W1N2476472W035658
77	W1N2476472W035689
78	W1N2476472W035742
79	W1N2476472W035778
80	W1N2476472W035980
81	W1N2476472W036120
82	W1N2476472W036141
83	W1N2476472W036439
84	W1N2476472W036450
85	W1N2476472W036517
86	W1N2476472W036583
87	W1N2476472W036667
88	W1N2476512W031108
89	W1N2476872W028783
90	W1N2476872W028890
91	W1N2476872W030180
92	W1N2476872W030345
93	W1N2476872W030430
94	W1N2476872W030607
95	W1N2476872W030665
96	W1N2476872W030691
97	W1N2476872W030752
98	W1N2476872W030829