

## Recall Detail

<b>Ref No</b>	<b>10000974</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	LEGEND/RL KA9
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Inspection of Driver 's Airbag Inflator
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	During of Driver airbag deployment, the inflator body may be ruptured due to excessive internal pressure.
<b>Remedial Action</b>	Inspection of Driver 's Airbag Inflator
<b>Build Dates</b>	1998-2000
<b>Launch Date</b>	03 NOV 2020
<b>Tentative Date of Recall Completion</b>	03 NOV 2027

JH4KA9640WC-200001  
 JH4KA9640WC-200002  
 JH4KA9640WC-200003  
 JH4KA9640WC-200004  
 JH4KA9640WC-200005  
 JH4KA9640WC-200006  
 JH4KA9640WC-200007  
 JH4KA9640WC-200079  
 JH4KA9640WC-200080  
 JH4KA9640WC-200081  
 JH4KA9640WC-200082  
 JH4KA9640WC-200083  
 JH4KA9640WC-200084  
 JH4KA9640WC-200085  
 JH4KA9640WC-200086  
 JH4KA9640WC-200297  
 JH4KA9640WC-200298  
 JH4KA9640WC-200299  
 JH4KA9640WC-200300  
 JH4KA9640WC-200301  
 JH4KA9640WC-200302

JH4KA9640WC-200303  
 JH4KA9640WC-200304  
 JH4KA9640WC-200305  
 JH4KA9640WC-200306  
 JH4KA9640WC-200307  
 JH4KA9640WC-200308  
 JH4KA9640WC-200309  
 JH4KA9640WC-200310  
 JH4KA9640WC-200311  
 JH4KA9640WC-200362  
 JH4KA9640WC-200363  
 JH4KA9640WC-200498  
 JH4KA9640WC-200499  
 JH4KA9640WC-200500  
 JH4KA9640WC-200589  
 JH4KA9640WC-200590  
 JH4KA9640WC-200591  
 JH4KA9640WC-200592  
 JH4KA9640WC-200593  
 JH4KA9640WC-202404  
 JH4KA9640WC-202405

JH4KA9640WC-202406  
JH4KA9640WC-202407  
JH4KA9640WC-202454  
JH4KA9640WC-202455  
JH4KA9640WC-202456  
JH4KA9640WC-202529  
JH4KA9640WC-202530  
JH4KA9640WC-202531  
JH4KA9640WC-202532  
JH4KA9640WC-202533  
JH4KA9640WC-202543  
JH4KA9640WC-202544  
JH4KA9640WC-202558  
JH4KA9640WC-202559  
JH4KA9640WC-202560  
JH4KA9640WC-202561  
JH4KA9640WC-202562  
JH4KA9640WC-202563  
JH4KA9640WC-202901  
JH4KA9640WC-202902  
JH4KA9640WC-202903  
JH4KA9640WC-202904  
JH4KA9640WC-202905  
JH4KA9640WC-202906  
JH4KA9640WC-202907  
JH4KA9640WC-202908  
JH4KA9640WC-202909  
JH4KA9640WC-202910  
JH4KA9640XC201279  
JH4KA9640XC201802  
JH4KA9640XC201846  
JH4KA9640XC201930  
JH4KA9640XC201931  
JH4KA9640XC201932  
JH4KA9640XC201933  
JH4KA9640XC201934  
JH4KA9640XC201935  
JH4KA9640XC201936  
JH4KA9640XC201949

JH4KA9640XC202099  
JH4KA9640XC202100  
JH4KA9640XC202101  
JH4KA9640XC202119  
JH4KA9640XC202120  
JH4KA9640XC202131  
JH4KA9640XC202147  
JH4KA9640XC202148  
JH4KA9640XC202175  
JH4KA9640XC202176  
JH4KA9640YC200049  
JH4KA9640YC200050  
JH4KA9640YC200087  
JH4KA9640YC200113  
JH4KA9640YC200114  
JH4KA9640YC200115  
JH4KA9640YC200116  
JH4KA9640YC200121  
JH4KA9640YC200122  
JH4KA9640YC200135  
JH4KA9640YC200136  
JH4KA9640YC200137  
JH4KA9640YC200138  
JH4KA9640YC200139  
JH4KA9640YC200140  
JH4KA9640YC200169  
JH4KA9640YC200170  
JH4KA9640YC200178  
JH4KA9640YC200179  
JH4KA9640YC200296  
JH4KA9640YC200310  
JH4KA9640YC200318  
JH4KA9640YC200330  
JH4KA9640YC200334