

Recall Detail	
Ref No.	10000977
Manufacturer	Land Rover
Vehicle Class	M1 – Private Car
Model/Type	Discovery Sport(LC) & Evoque(LZ)
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / service@landrover.com.hk)
Subject	Software Updates
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A DC-DC convertor of MHEV system may overload causes battery warning lamp illuminated. In extreme case, vehicle occupants may notice a burning smell and/or smoke inside the passenger compartment.
Remedial Action	Update new software
Build Dates	25 May 2018 to 2 Oct 2020
Launch Date	16 November 2020
Tentative Date of Recall Completion	31 December 2025

1. SALCA2AX0LH838285
2. SALCA2AX0LH850730
3. SALCA2AX0LH851683
4. SALCA2AX0LH873635
5. SALCA2AX1LH833368
6. SALCA2AX1LH838389
7. SALCA2AX2LH872762
8. SALCA2AX2LH872793
9. SALCA2AX3LH833372
10. SALCA2AX3LH841374
11. SALCA2AX5LH838296
12. SALCA2AX5LH839576
13. SALCA2AX6LH837643
14. SALCA2AX6LH841708
15. SALCA2AX8LH839667
16. SALCA2AX9LH837457
17. SALCA2AXXLH833109
18. SALCA2AXXLH835314
19. SALCA2AXXLH872735
20. SALZA2AX2LH063076

21. SALZA2AX4LH045792
22. SALZA2AX7LH020773
23. SALZA2AX8LH041177
24. SALZA2AX8LH044399