

## Recall Detail

<b>Ref No</b>	<b>10000981</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	GLE / 167
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Rear double seat belt buckle (9290005)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>in certain circumstances the middle seatbelt buckle of affected vehicles could be pushed into the gap between the vehicle body and the seat cushion while buckling up.</p> <p>If the passenger is not able to retrieve the buckle, the affected seat would not be available for fastening. If a passenger does not fasten the seatbelt according to the Operator's Manual, the risk of injury in a crash could increase.</p>
<b>Remedial Action</b>	Adjust the positioning of the double buckle on affected vehicles as a precautionary measure.
<b>Build Dates</b>	06/03/2019 - 24/07/2020
<b>Launch Date</b>	11/11/2020
<b>Tentative Date of Recall Completion</b>	31/03/2021

3	W1N1671592A145556	43	WDC1671592A083363
4	W1N1671592A146143	44	WDC1671592A083392
5	W1N1671592A147386	45	WDC1671592A084120
6	W1N1671592A157495	46	WDC1671592A084273
7	W1N1671592A158322	47	WDC1671592A084667
8	W1N1671592A158483	48	WDC1671592A084950
9	W1N1671592A204038	49	WDC1671592A085880
10	W1N1671592A208941	50	WDC1671592A086705
11	W1N1671592A249300	51	WDC1671592A087734
12	W1N1673612A265988	52	WDC1671592A090769
13	W1N1673612A268298	53	WDC1671592A090948
14	WDC1671592A026642	54	WDC1671592A091515
15	WDC1671592A028764	55	WDC1671592A093031
16	WDC1671592A030127	56	WDC1671592A095778
17	WDC1671592A037249	57	WDC1671592A096989
18	WDC1671592A037677	58	WDC1671592A100580
19	WDC1671592A040897	59	WDC1671592A106554
20	WDC1671592A043263	60	WDC1671592A106946
21	WDC1671592A043312	61	WDC1671592A108336
22	WDC1671592A043644	62	WDC1671592A108443
23	WDC1671592A043727	63	WDC1671592A108795
24	WDC1671592A043807	64	WDC1671592A115200
25	WDC1671592A043841	65	WDC1671592A115460
26	WDC1671592A043852	66	WDC1671592A119159
27	WDC1671592A044154	67	WDC1671592A119596
28	WDC1671592A044422	68	WDC1671592A121631
29	WDC1671592A044760	69	WDC1671592A123052
30	WDC1671592A044922	70	WDC1671592A130890
31	WDC1671592A044926	71	WDC1671592A135200
32	WDC1671592A045973	72	WDC1671592A141228
33	WDC1671592A050156	73	WDC1673612A135765
34	WDC1671592A063465	74	WDC1673612A136892
35	WDC1671592A064312	75	WDC1673612A137729
36	WDC1671592A064380		
37	WDC1671592A064817		
38	WDC1671592A064884		
39	WDC1671592A065627		
40	WDC1671592A065677		
41	WDC1671592A075147		
42	WDC1671592A081584		