

Recall Detail

Ref No	10000984
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	C-HR
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Brake Pedal Bracket Tightening Bolt
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The subject vehicles have a brake pedal that is mounted to the firewall and reinforced with a bracket that is attached to the instrument panel structure with a bolt. There is a possibility that the bolt on this bracket may not have been torqued to within the design specified range due to a defective nut runner (bolt torquing tool).</p> <p>If the bolt becomes sufficiently loose over time, the brake pedal could move toward the driver during a crash, increasing the risk of injury to the driver. In addition, if the driver applies high force to the brake pedal repeatedly over time with the bolt in the loose condition, the mounting location of the brake pedal on the firewall may eventually deform and crack, altering the position of the brake pedal and increasing in physical distance between the brake pedal and driver foot. This can lead to an increase the risk of a crash.</p>
Remedial Action	Inspect and, if necessary, tighten the bolt
Build Dates	November 2019 to May 2020
Launch Date	November 2020
Tentative Date of Recall Completion	December 2021

1	NMTKZ3BX60R351730	18	NMTKZ3BX30R351703
2	NMTKZ3BX10R351232	19	NMTKZ3BX60R351498
3	NMTKZ3BX50R352156	20	NMTKZ3BX70R351672
4	NMTKZ3BX90R350586	21	NMTKZ3BX90R351074
5	NMTKZ3BX30R351944	22	NMTKZ3BX90R351415
6	NMTKZ3BX00R351111	23	NMTKZ3BX90R351642
7	NMTKZ3BX90R351706	24	NMTKZ3BX00R351139
8	NMTKZ3BX70R351249	25	NMTKZ3BX00R351447
9	NMTKZ3BX00R351254	26	NMTKZ3BX00R352047
10	NMTKZ3BX50R352173	27	NMTKZ3BX20R351238
11	NMTKZ3BX70R352014	28	NMTKZ3BX20R351403
12	NMTKZ3BX30R352186	29	NMTKZ3BX20R351420
13	NMTKZ3BX50R351024	30	NMTKZ3BX20R351546
14	NMTKZ3BXX0R351049	31	NMTKZ3BX20R351949
15	NMTKZ3BX00R351433	32	NMTKZ3BX30R351491
16	NMTKZ3BX10R352011	33	NMTKZ3BX30R352043
17	NMTKZ3BX20R351904	34	NMTKZ3BX30R352138

35	NMTKZ3BX40R351600
36	NMTKZ3BX40R351872
37	NMTKZ3BX50R351119
38	NMTKZ3BX50R351282
39	NMTKZ3BX50R351864
40	NMTKZ3BX50R351900
41	NMTKZ3BX60R351193
42	NMTKZ3BX60R351307
43	NMTKZ3BX60R351694
44	NMTKZ3BX60R351758
45	NMTKZ3BX70R350862
46	NMTKZ3BX70R351039
47	NMTKZ3BX70R351218
48	NMTKZ3BX70R351221
49	NMTKZ3BX70R351252
50	NMTKZ3BX70R351512
51	NMTKZ3BX70R351607
52	NMTKZ3BX70R351719
53	NMTKZ3BX70R351784
54	NMTKZ3BX70R351848
55	NMTKZ3BX70R351963
56	NMTKZ3BX70R352112
57	NMTKZ3BX80R351308
58	NMTKZ3BX80R351678
59	NMTKZ3BX80R351681
60	NMTKZ3BX80R351888
61	NMTKZ3BX80R352118
62	NMTKZ3BX90R351303
63	NMTKZ3BX90R351463
64	NMTKZ3BX90R351947
65	NMTKZ3BX90R351964
66	NMTKZ3BX90R351995
67	NMTKZ3BX90R352127
68	NMTKZ3BX90R352192
69	NMTKZ3BXX0R351245
70	NMTKZ3BXX0R351293
71	NMTKZ3BXX0R351780
72	NMTKZ3BXX0R352055
73	NMTKZ3BXX0R352167
74	NMTKZ3BX60R352165
75	NMTKZ3BX00R350671

76	NMTKZ3BX10R350601
77	NMTKZ3BX10R350694
78	NMTKZ3BX10R350825
79	NMTKZ3BX10R351375
80	NMTKZ3BX20R351062
81	NMTKZ3BX20R351210
82	NMTKZ3BX20R351854
83	NMTKZ3BX40R350625
84	NMTKZ3BX40R350639
85	NMTKZ3BX40R351628
86	NMTKZ3BX50R350715
87	NMTKZ3BX50R351363
88	NMTKZ3BX60R350934
89	NMTKZ3BX60R351159
90	NMTKZ3BX60R351565
91	NMTKZ3BX70R351171
92	NMTKZ3BX70R351378
93	NMTKZ3BX70R351834
94	NMTKZ3BX80R351079
95	NMTKZ3BX90R350975
96	NMTKZ3BX90R351026
97	NMTKZ3BX90R351351
98	NMTKZ3BX90R351379
99	NMTKZ3BX90R351401
100	NMTKZ3BX90R351561
101	NMTKZ3BX90R351608
102	NMTKZ3BXX0R351102
103	NMTKZ3BXX0R351326
104	NMTKZ3BXX0R351634
105	NMTKZ3BXX0R351830