

Recall Detail

Ref No	10000991
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	GLC 63 S 4MATIC / 253
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Wiring harness at starter (5491301)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The threaded connection of the positive line at the starter in affected vehicles may not correspond with the specification. In this case, the positive line may be in contact with the starter, become chafed due to relative movements, and cause a short circuit.</p> <p>Depending on the type of short circuit, a vehicle breakdown and/or a potential fire hazard cannot be ruled out completely.</p>
Remedial Action	Check the threaded connection of the positive line at the starter in affected vehicles as a precautionary measure and correct if necessary.
Build Dates	22/02/2018 - 02/04/2019
Launch Date	29/01/2021
Tentative Date of Recall Completion	30/06/2021

3	WDC2533892F474697
4	WDC2533892F501964
5	WDC2533892F515808
6	WDC2533892F636500
7	WDC2539881F527507
8	WDC2539892F422316
9	WDC2539892F507226
10	WDC2539892F508614
11	WDC2539892F511381
12	WDC2539892F516443