

## Recall Detail

<b>Ref No</b>	<b>10000996</b>
<b>Manufacturer</b>	Bentley
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	New Continental GTC
<b>Dealer (phone no)</b>	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
<b>Subject</b>	New Continental GTC – Comfort system control module – Software parameter update
<b>Progress</b>	In process
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Actuation (closing and opening of the convertible roof) with the remote-control Key Fob can occur at distances greater than 6 meters which contravenes an internal safety guidance measure. It prevent the potential injury of a third-party during convertible roof opening / closing using the key fob.
<b>Remedial Action</b>	Software parameter update to the Comfort system control module, the update will remove the ability to activate the convertible roof via the key fob.
<b>Build Dates</b>	May 2019 - Nov 2020
<b>Launch Date</b>	10 Feb 2021
<b>Tentative Date of Recall Completion</b>	

VIN	VIN
SCBDA33S1LC079908	SCBDS33S5LC078886
SCBDA33S1LC080718	SCBDS33S4LC079091
SCBDS33S1LC076861	SCBDJ33S6LC084375
SCBDS33S8LC076954	SCBDS33S6LC076385
SCBDA33S5LC077255	SCBDS33SXLC076602
SCBDS33S3LC077266	SCBDS33SXLC077328
SCBDS33S3LC077302	SCBDS33S4LC078541
SCBDS33S6LC077536	SCBDS33S9LC081029
SCBDS33S3LC077686	SCBDS33S5LC081903
SCBDS33S5LC078757	SCBDJ33S0LC084355