

Recall Detail

Ref No	10001001
Manufacturer	Honda
Vehicle Class	Private Car
Model/Type	CR-V RW2
Dealer (phone no)	22168183
Subject	Replace of Fuel Pump Kit
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Affected vehicles may be equipped with a fuel pump module manufactured with low density impellers. If the surface of the lower density impeller is exposed to production solvent drying for longer periods of time, higher levels of surface cracking may occur. These cracks may lead to excessive fuel absorption, resulting in impeller deformation. Over time, if an impeller deforms to a point that creates sufficient interference with the fuel pump body, the fuel pump becomes inoperative, which may cause illumination of the Malfunction Indicator Lamp in the instrument panel. Fuel pump inoperability could prevent an engine from starting or stall an engine while driving, increasing the risk of a crash.
Remedial Action	Replace of Fuel Pump Kit
Build Dates	2019
Launch Date	26 APR 2021
Tentative Date of Recall Completion	26 APR 2028

MRHRW2840KP030003
 MRHRW2840KP030004
 MRHRW2840KP030005
 MRHRW2840KP030006
 MRHRW2840KP030007
 MRHRW2840KP030008
 MRHRW2840KP030009
 MRHRW2840KP030010
 MRHRW2840KP030011
 MRHRW2840KP030012
 MRHRW2840KP030013
 MRHRW2840KP030014
 MRHRW2840KP030015
 MRHRW2840KP030016
 MRHRW2840KP030017

MRHRW2840KP030019
 MRHRW2840KP030020
 MRHRW2840KP030021
 MRHRW2840KP030022
 MRHRW2840KP030023
 MRHRW2840KP030024
 MRHRW2840KP030025
 MRHRW2840KP030026
 MRHRW2840KP030027
 MRHRW2840KP030028
 MRHRW2840KP030029
 MRHRW2840KP030030
 MRHRW2840KP030031
 MRHRW2840KP030032
 MRHRW2840KP030033

MRHRW2840KP030034
MRHRW2840KP030035
MRHRW2840KP030036
MRHRW2840KP030037
MRHRW2840KP030038
MRHRW2840KP030039
MRHRW2840KP030040
MRHRW2840KP030041
MRHRW2840KP030042
MRHRW2840KP030043
MRHRW2840KP030044
MRHRW2840KP030045
MRHRW2840KP030046
MRHRW2840KP030047
MRHRW2840KP030048
MRHRW2840KP030049
MRHRW2840KP030050
MRHRW2840KP030052
MRHRW2840KP030053
MRHRW2840KP030054
MRHRW2840KP030055
MRHRW2840KP030056
MRHRW2840KP030057
MRHRW2840KP030060
MRHRW2840KP030061
MRHRW2840KP030062
MRHRW2840KP030063
MRHRW2840KP030064
MRHRW2840KP030067
MRHRW2840KP030068
MRHRW2840KP030069
MRHRW2840KP030070
MRHRW2840KP030071
MRHRW2840KP030072
MRHRW2840KP030073
MRHRW2840KP030074
MRHRW2840KP030075
MRHRW2840KP030076
MRHRW2840KP030077

MRHRW2840KP030079
MRHRW2840KP030080
MRHRW2840KP030081
MRHRW2840KP030082
MRHRW2840KP030083
MRHRW2840KP030084
MRHRW2840KP030085
MRHRW2840KP030086
MRHRW2840KP030087
MRHRW2840KP030088
MRHRW2840KP030089
MRHRW2840KP030090
MRHRW2840KP030091
MRHRW2840KP030092
MRHRW2840KP030093
MRHRW2840KP030094
MRHRW2840KP030095
MRHRW2840KP030096
MRHRW2840KP030097