

Recall Detail

Ref No	10001008
Manufacturer	ISUZU
Vehicle Class	Commercial vehicle
Model/Type	ISUZU N series
Dealer (phone no)	Triangle Motors Ltd (Tele: 2216 8163)
Subject	ISUZU N Series Rear Axle U-bolt Nut Inspection and Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The rear axle U-bolt nut might not be tightened with proper torque. In the worst case, the vehicle becomes inoperable.
Remedial Action	Inspect rear axle U-bolt nut. If any looseness of U-bolt nut is found, replace all rear axle U-bolt and relating fastener parts.
Build Dates	2015 -2019
Launch Date	10 /05/2021
Tentative Date of Recall Completion	09/05/2026

N series

1	JAANPR75HK7100867	11	JAANPR75KK7101355	21	JAANPR75KG7102124
2	JAANPR75HK7100887	12	JAANPR75KK7101359	22	JAAN1R75KG7100481
3	JAANPR75HK7100888	13	JAANPR75KK7101361	23	JAANPR75KG7102125
4	JAANPR75HK7100889	14	JAANPR75KK7101366	24	JAANPR75KG7102126
5	JAANPR75KK7101315	15	JAANPR75KK7101369	25	JAAN1R75LH7100159
6	JAANPR75KK7101320	16	JAANPR75KK7101372	26	JAAN1R75LF7102516
7	JAANPR75KK7101322	17	JAANPR75KK7101376	27	JAANPR75HF7104678

8.	JAANPR75KK7101324	18	JAAN1R75LJ7100774	28	JAAN1R75KF7100477
9.	JAANPR75KK7101346	19	JAAN1R75KH7100512	29	JAANPR75KF7105674
10.	JAANPR75KK7101349	20	JAAN1R75LH7100923		