

Recall Detail	
Ref No	10001018
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Sienta HV / NHP170R
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Inverter Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	In a hybrid system, since the power conversion module control board has insufficient resistance to electrical noise, the power supply control circuit may erroneously detect the electrical noise, generated by the voltage fluctuation of the high voltage circuit, as an abnormality and stop momentarily. Therefore, the power supply voltage may drop momentarily, the engine warning light may be turned on and a momentary power loss may occur.
Remedial Action	Replace the inverter
Build Dates	21 Jan 2021 to 8 April 2021
Launch Date	7 June 2021
Tentative Date of Recall Completion	31 July 2022

1	JTDZZ9H300L000725
2	JTDZZ9H310L000734
3	JTDZZ9H320L000726
4	JTDZZ9H340L000727
5	JTDZZ9H340L000730
6	JTDZZ9H350L000722
7	JTDZZ9H360L000728
8	JTDZZ9H370L000723
9	JTDZZ9H380L000729
10	JTDZZ9H390L000741