

Recall Detail

Ref No	10001045
Manufacturer	Kia
Vehicle Class	Private Car
Model/Type	Sportage (QL)
Dealer (phone no)	2462 4621
Subject	Junction Box HECU Fuse Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	New spec for HECU fuse to avoid over current
Remedial Action	Junction Box HECU Fuse Replacement & *S/W Upgrade *(S/W Upgrade only apply to EPB type)
Build Dates	Mar 19, 2015 - Oct 23, 2020
Launch Date	May 28, 2021
Tentative Date of Recall Completion	May 28, 2025

KNAPN813SH7338675
KNAPN813SH7369559
KNAPN813SH7369740
KNAPN813SH7384122
KNAPN813SH7384261
KNAPN813SH7384451
KNAPN81AMG7053654
KNAPN81AMG7132581
KNAPN81AMG7141856
KNAPN81AMG7159079
KNAPN81AMG7159307
KNAPN81AMG7176465
KNAPN81AMG7192712
KNAPN81AMH7201741
KNAPN81AMH7202073
KNAPN81AMH7215890
KNAPN81AMH7216227
KNAPN81AMH7256802
KNAPN81AMH7304574
KNAPN81AMH7332706

KNAPN81AMH7333048
KNAPN81AMH7333070
KNAPN81AMH7333213
KNAPN81AMH7343562
KNAPN81AMJ7416347
KNAPN81AMJ7459342
KNAPN81AMJ7459612
KNAPN81AMJ7466546
KNAPN81AMJ7466578
KNAPN81AMJ7495860
KNAPN81AMJ7496356
KNAPN81AMK7561376
KNAPN81AMK7563281
KNAPN81AMK7563442
KNAPN81AMK7563739
KNAPN81AMK7563762
KNAPN81AMK7601377
KNAPN81AMK7601699
KNAPN81AMK7601841
KNAPN81AMK7641192

KNAPN81AMK7722392
KNAPN81CSG7053209
KNAPN81CSG7053302
KNAPN81CSG7133162
KNAPN81CSH7218330
KNAPN81CSH7218943
KNAPN81CSH7303222
KNAPN81CSH7303751
KNAPN81CSH7303798
KNAPN81CSH7317367
KNAPN81CSH7332652
KNAPN81CSK7601509
KNAPR81AMK7641483
KNAPR81AMK7641753
KNAPR81AMK7689226
KNAPR81AML7746809
KNAPR81AML7746971
KNAPR81AML7755638
KNAPR81AML7755728
KNAPR81AML7804658
KNAPR81AML7816681
KNAPR81AML7825935
KNAPR81AML7850590
KNAPR81AMM7868626
KNAPR81AMM7868630