

Recall Detail

Ref No	10001058
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Bentayga 5 seat variant
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
Subject	2nd row seats may not be correctly aligned and locked on all seat rails
Progress	In process
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It is possible that if one of the seat rails is not correctly locked, it could move in the event of a crash, compromising occupant safety.
Remedial Action	An additional track stop is now fitted to each of the inboard seat rails. A "go / no go" gauge has been introduced to the process to ensure seat rails are correctly aligned immediately prior to fastening them to the body. A further improvement is imminent to include a clamp to prevent movement of seat/rail once the rails are confirmed as correctly aligned.
Build Dates	From June 2020 and March 2022
Launch Date	20 Apr 2022
Tentative Date of Recall Completion	20 Apr 2024

1	SJAAB14V1MC033086
2	SJAAB14V3MC033087
3	SJAAB14VXMC033362
4	SJAAB14V5MC034841
5	SJAAB14V0MC033001
6	SJAAB14V9MC036592
7	SJAAB14V9MC033465
8	SJAA514V5NC011908
9	SJAA514V8NC011949
10	SJAA414V6NC012052
11	SJAA514V8NC012289
12	SJAA514V7NC011943
13	SJAAB14V1MC033315
14	SJAAB14V1MC036666
15	SJAA414V8MC038103
16	SJAA414VXMC038510
17	SJAAB14V8MC033344
18	SJAAB14V7MC038969
19	SJAAB14V2MC033808
20	SJAAB14V7MC033366