

Recall Detail

Ref No	10001077
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Medium Goods Vehicle
Model/Type	Fuso FK62F, FN63F, FM65F
Dealer (phone no)	Universal Cars Limited (Tel: 39138818)
Subject	Inspect/ reprogramming of ABS unit software
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	During our quality monitoring it was revealed that stop lamp not lighted conditions caused by software bug inside ABS ECU. In the worst case, rear end collision by behind traffic due to no illumination of stop lamps.
Remedial Action	Check the software of correct version or reprogramming ABS unit software.
Build Dates	From 09/ 10/ 2020 to 29/ 06/ 2021
Launch Date	XX/ 07/ 2022
Tentative Date of Recall Completion	XX/ 07/ 2025

1	FK62FGA20066
2	FK62FKA20058
3	FK62FKA20059
4	FK62FKA20060
5	FK62FKA20061
6	FK62FKA20062
7	FK62FKA20063
8	FK62FKA20065
9	FK62FKA20064
10	FK62FKA20066
11	FM65FMA20156
12	FM65FMA20157
13	FM65FPA20052
14	FM65FPA20053
15	FM65FPA20054
16	FM65FPA20055
17	FM65FPA20056
18	FM65FPA20057
19	FM65FPA20058

20	FM65FPA20059
21	FM65FPA20061
22	FM65FPA20062
23	FM65FPA20063
24	FM65FPA20064
25	FM65FPA20065
26	FM65FPA20066
27	FM65FPA20067
28	FM65FPA20068
29	FM65FPA20060
30	FN63FUA31009
31	
32	
33	
34	
35	
36	
37	
38	

