

Recall Detail

Ref No	10001079
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Heavy Goods Vehicle
Model/Type	Fuso FV70H, FP74H, FP70H
Dealer (phone no)	Universal Cars Limited (Tel: 39138818)
Subject	Remove diode from trailer stop lamp circuit and add relay
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>During our quality monitoring it was revealed that the diode equipped with trailer stop lamp circuit burned out due to insufficient capacity. This will cause the trailer side brake lamp to not light up, and no indication to following vehicle and hence risk of accident.</p> <p>In the worst case, rear end collision by behind traffic due to no illumination of stop lamps.</p>
Remedial Action	Remove diode from trailer stop lamp circuit and add relay .
Build Dates	From 22/12/2017 to 16/02/2021
Launch Date	01/08/2022
Tentative Date of Recall Completion	01/08/2025

1	FV70HJA00003
2	FP74HDA00001
3	FP74HDA00003
4	FV70HJA00036
5	FP74HDA00011
6	FP74HDA00013
7	FV70HJA00106
8	FV70HJA00110
9	FP74HDA00015
10	FP74HDA00017
11	FP74HDA00019
12	FP74HDA00018
13	FP74HDA00020
14	FP74HDA00021
15	FP74HDA00022
16	FP74HDA00023
17	FP74HDA00024
18	FP74HDA00025

19	FP74HDA00026
20	FP74HDA00027
21	FP70HDA00044
22	FP70HDA00045
23	FP70HDA00046
24	FP70HDA00047
25	FV70HJA10063
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	

