

Recall Detail

Ref No	10001093
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	GLS/ 167
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	3rd seat row locking mechanism (9391001)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	As part of constant monitoring, we have determined in certain vehicles that the springs in the locking mechanism of the seat backrest of the third seat row may not have been installed in accordance with the specifications. In the case of an accident, a failure of the seat backrest locking function cannot be completely ruled out. This would increase the risk of injury for the occupants. The basic function of the seat backrest locking function would, as envisaged, still be given.
Remedial Action	As a precautionary measure, to check the lock on 3rd seat row in the affected vehicles and replace the seat backrest if necessary.
Build Dates	13/09/2019 – 01/03/2022
Launch Date	24/10/2022
Tentative Date of Recall Completion	31/12/2023

3	W1N1679561A699726	43	W1N1679592A488247
4	W1N1679561A699736	44	W1N1679592A488258
5	W1N1679571A434653	45	W1N1679592A495612
6	W1N1679591A147515	46	W1N1679592A498173
7	W1N1679591A181480	47	W1N1679592A498189
8	W1N1679591A192889	48	W1N1679592A517695
9	W1N1679591A246572	49	W1N1679592A520991
10	W1N1679591A247433	50	W1N1679592A535972
11	W1N1679591A542179	51	W1N1679592A535980
12	W1N1679591A562792	52	W1N1679592A557846
13	W1N1679591A562806	53	W1N1679592A562077
14	W1N1679591A569784	54	W1N1679592A592891
15	W1N1679591A578198	55	W1N1679592A592905
16	W1N1679591A618303	56	W1N1679592A592921
17	W1N1679591A641506	57	W1N1679592A608033
18	W1N1679591A664001	58	W1N1679592A614486
19	W1N1679591A696962	59	W1N1679592A638514
20	W1N1679591A697128	60	W1N1679892A287107
21	W1N1679591A697317	61	W1N1679892A298353
22	W1N1679591A697474	62	W1N1679892A298853
23	W1N1679592A364811	63	W1N1679892A454087
24	W1N1679592A412293	64	W1N1679892A519729
25	W1N1679592A414791	65	WDC1679591A112726
26	W1N1679592A421522		
27	W1N1679592A421531		
28	W1N1679592A440205		
29	W1N1679592A440213		
30	W1N1679592A440225		
31	W1N1679592A441615		
32	W1N1679592A441623		
33	W1N1679592A447297		
34	W1N1679592A447312		
35	W1N1679592A447324		
36	W1N1679592A455315		
37	W1N1679592A458638		
38	W1N1679592A458644		
39	W1N1679592A465247		
40	W1N1679592A481785		
41	W1N1679592A488220		
42	W1N1679592A488235		