

## Recall Detail

<b>Ref No</b>	<b>10001106</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Light Goods Vehicle (Van)
<b>Model/Type</b>	V-Class, Vito/ 447 with OM654 engine
<b>Dealer (phone no)</b>	Fanling Commercial Vehicle Service Centre: 2637 2988 Lau Fau Shan Commercial Vehicle Service Centre: 2111 7428
<b>Subject</b>	Routing of fuel filter drain pipe (0992007)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>Due to a deviation in the production process, the drain pipe may not have been routed in accordance with the specification. In this case, the drain pipe may be in contact with the underfloor paneling and chafe during driving operation. As a result, diesel fuel may leak and cause a distinctly noticeable fuel odor. The fuel leak may increase over the further course of time. Depending on the amount that leaks out, this could increase the risk of accident for the following traffic. A fire hazard can be ruled out, as there are no hot components located near the drain pipe or in areas into which leaking fuel may enter.</p>
<b>Remedial Action</b>	As a precautionary measure, to replace the drain pipe with a screw plug for draining the fuel filter.
<b>Build Dates</b>	08/11/2021 – 13/04/2022
<b>Launch Date</b>	23/01/2023
<b>Tentative Date of Recall Completion</b>	31/12/2023

1	W1V44760523988456	41	W1V44770324109309
2	W1V44770323940132	42	W1V44770324109341
3	W1V44770323940353	43	W1V44770324109362
4	W1V44770323973121	44	W1V44770324109426
5	W1V44770323973741	45	W1V44770324109439
6	W1V44770323983840	46	W1V44770324109695
7	W1V44770323983883	47	W1V44770324109722
8	W1V44770323984483	48	W1V44770324109726
9	W1V44770323985061	49	W1V44770324109744
10	W1V44770323985088	50	W1V44770324109773
11	W1V44770323985230	51	W1V44770324110105
12	W1V44770323985334	52	W1V44770324110897
13	W1V44770323985414	53	W1V44770324110944
14	W1V44770323985613	54	W1V44770324111501
15	W1V44770323987439	55	W1V44770523940277
16	W1V44770323987667	56	W1V44770523940404
17	W1V44770323987732	57	W1V44770523940553
18	W1V44770323988158	58	W1V44770523975398
19	W1V44770323988206	59	W1V44770523983461
20	W1V44770323988353	60	W1V44770523983613
21	W1V44770323988368	61	W1V44770523983806
22	W1V44770323988412	62	W1V44770523983875
23	W1V44770323988416	63	W1V44770523984074
24	W1V44770323988472	64	W1V44770523984247
25	W1V44770323988490	65	W1V44770523984474
26	W1V44770323988762	66	W1V44770523984526
27	W1V44770323988813	67	W1V44770523984597
28	W1V44770323988817	68	W1V44770523984635
29	W1V44770323988839	69	W1V44770523984639
30	W1V44770323988968	70	W1V44770523984733
31	W1V44770323989069	71	W1V44770523984792
32	W1V44770323989140	72	W1V44770523984801
33	W1V44770323989187	73	W1V44770523984827
34	W1V44770323989235	74	W1V44770523984853
35	W1V44770324108014	75	W1V44770523985037
36	W1V44770324108099	76	W1V44770523985081
37	W1V44770324108607	77	W1V44770523985122
38	W1V44770324108744	78	W1V44770523985153
39	W1V44770324108856	79	W1V44770523985234
40	W1V44770324108860	80	W1V44770523985318

81	W1V44770523985346
82	W1V44770523985395
83	W1V44770523985508
84	W1V44770523985756
85	W1V44770523985910
86	W1V44770523986362
87	W1V44770523986407
88	W1V44770523986455
89	W1V44770523988270
90	W1V44770523988573
91	W1V44770523988650
92	W1V44770523988834
93	W1V44770523988851
94	W1V44770523988921
95	W1V44770523988987
96	W1V44770523988999
97	W1V44770523989018
98	W1V44770523989024
99	W1V44770523989087
100	W1V44770523989090
101	W1V44770523989096
102	W1V44770523989159
103	W1V44770523989196
104	W1V44770523989221
105	W1V44770523989252
106	W1V44770524101548
107	W1V44770524101727
108	W1V44770524101923
109	W1V44770524101944
110	W1V44770524102033
111	W1V44770524102098
112	W1V44770524102169
113	W1V44770524103489
114	W1V44770524107676
115	W1V44770524108532
116	W1V44770524108550
117	W1V44770524108765
118	W1V44770524109137
119	W1V44770524109167
120	W1V44770524109275

121	W1V44770524109299
122	W1V44770524109358
123	W1V44770524109428
124	W1V44770524109441
125	W1V44770524109678
126	W1V44770524110141
127	W1V44770524110426
128	W1V44770524110475
129	W1V44770524110478
130	W1V44770524110502
131	W1V44770524110622
132	W1V44770524110770
133	W1V44770524111517
134	W1V44770524111583