

## Recall Detail

<b>Ref No</b>	<b>10001117</b>
<b>Manufacturer</b>	Bentley
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	New Continental GT Convertible
<b>Dealer (phone no)</b>	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
<b>Subject</b>	Left & right front seat airbag deflector bracket-Sharp Edge On Airbag Deflector Bracket Rivet
<b>Progress</b>	In process
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Bentley has discovered that when riveting the airbag deflector bracket to the seat frame on Continental GTC vehicles, a sharp edge on the rivet could be created. Potential risk of damage to the front seat airbag during deployment.
<b>Remedial Action</b>	Inspect the affected front seats and, if necessary, remove the sharp edge on the airbag deflector bracket rivet.
<b>Build Dates</b>	December 2018 to January 2021
<b>Launch Date</b>	10 APRIL 2023
<b>Tentative Date of Recall Completion</b>	

VIN	
SCBDA33S2KC073744	SCBDS33S4LC078541
SCBDA33S6KC073827	SCBDS33S5LC078757
SCBDA33S7KC073965	SCBDS33S5LC078886
SCBDA33S3KC074305	SCBDS33S4LC079091
SCBDA33S0KC074343	SCBDA33S1LC079908
SCBDA33S4KC074667	SCBDA33S1LC080718
SCBDA33S6KC074671	SCBDS33S9LC081029
SCBDA33S5KC074855	SCBDS33S5LC081903
SCBDS33S6LC076385	SCBDJ33S0LC084355
SCBDS33SXLC076602	SCBDJ33S6LC084375
SCBDS33S1LC076861	
SCBDS33S8LC076954	
SCBDA33S5LC077255	
SCBDS33S3LC077266	
SCBDS33S3LC077302	
SCBDS33SXLC077328	
SCBDS33S6LC077536	
SCBDS33S3LC077686	