

Recall Detail	
Ref No.	10001132
Manufacturer	Jaguar
Vehicle Class	M1 – Private Car
Model/Type	I-Pace (DH)
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / info@jaguar.com.hk)
Subject	Battery Energy Control Module (BECM) software update
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Some vehicles have experienced thermal overload which may show as smoke or fire, which may occur underneath the vehicle where the High Voltage (HV) battery is located.
Remedial Action	Update the Battery Energy Control Module (BECM) software
Build Dates	2019 to 2022
Launch Date	19 Jun 2023
Tentative Date of Recall Completion	31 December 2026

1.	SADHA2A10L1F85199
2.	SADHA2A11K1F72461
3.	SADHA2A11L1F84529
4.	SADHA2A11L1F84546
5.	SADHA2A11L1F84563
6.	SADHA2A11L1F84661
7.	SADHA2A12L1F85821
8.	SADHA2A13L1F84533
9.	SADHA2A13L1F87903
10.	SADHA2A13P1630140
11.	SADHA2A14K1F62376
12.	SADHA2A14L1F83259
13.	SADHA2A14L1F87831
14.	SADHA2A14N1622934
15.	SADHA2A15L1F84520
16.	SADHA2A15L1F84548
17.	SADHA2A15L1F87868
18.	SADHA2A15L1F87935
19.	SADHA2A15N1624689
20.	SADHA2A16L1600995
21.	SADHA2A16L1F83697

22.	SADHA2A17L1F88505
23.	SADHA2A19M1614147
24.	SADHA2A1XL1600532
25.	SADHA2A1XL1F84612
26.	SADHA2A1XL1F87901