

Recall Detail	
Ref No	10001140
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	5 series (F10) with B47O B47T B47U engine
Dealer (phone no)	31936688
Subject	Replacing exhaust-gas recirculation cooler
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The exhaust gas recirculation coolers can possibly leak over the service life of the vehicle.</p> <p>In the worst case, the exhaust gas recirculation cooler can leak. The escaping coolant could create flammable deposits combined with the soot and oil deposits in the exhaust-gas recirculation cooler. In rare cases, this could lead to local scorching on the intake system and, in extreme cases, a thermal incident can occur.</p>
Remedial Action	Replace exhaust-gas recirculation cooler
Build Dates	23/07/2014 – 02/06/2022
Launch Date	21/04/2023
Tentative Date of Recall Completion	31/12/2023

1|WBA5E52050G113450