

## Recall Detail

<b>Ref No</b>	<b>10001144</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	S-Class/ 223
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Bolting of main fuse box engine compartment (5491111)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affected by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	We have determined that a bolt connection in the engine compartment main fuse box on certain vehicles unfortunately might not meet specifications. In consequence, a thermal damage cannot be completely ruled out. Should the connection be interrupted, the vehicle could lose propulsion while driving. This would increase the risk of a crash.
<b>Remedial Action</b>	As a precautionary measure, to check the bolting connection in the engine compartment main fuse box in the affected vehicles and correct this if necessary.
<b>Build Dates</b>	13/10/2020 – 17/08/2022
<b>Launch Date</b>	16/08/2023
<b>Tentative Date of Recall Completion</b>	30/09/2024

1

W1K2231612A011596

3

W1K2231612A015426

2

W1K2231612A011713

4

W1K2231612A015582

5	W1K2231612A016020	45	W1K2231612A090854
6	W1K2231612A016039	46	W1K2231612A135185
7	W1K2231612A016346	47	W1K2231612A138651
8	W1K2231612A016851	48	W1K2231612A142687
9	W1K2231612A017029	49	W1K2231612A145519
10	W1K2231612A017844	50	W1K2231632A003355
11	W1K2231612A017912	51	W1K2231632A013090
12	W1K2231612A018039	52	W1K2231632A014543
13	W1K2231612A018240	53	W1K2231632A014930
14	W1K2231612A018335	54	W1K2231632A016550
15	W1K2231612A018856	55	W1K2231632A017995
16	W1K2231612A018892	56	W1K2231632A018030
17	W1K2231612A019771	57	W1K2231632A018165
18	W1K2231612A019971	58	W1K2231632A018279
19	W1K2231612A023446	59	W1K2231632A018347
20	W1K2231612A024373	60	W1K2231632A018374
21	W1K2231612A024385	61	W1K2231632A018644
22	W1K2231612A024749	62	W1K2231632A018849
23	W1K2231612A024783	63	W1K2231632A018993
24	W1K2231612A024830	64	W1K2231632A019009
25	W1K2231612A024858	65	W1K2231632A019028
26	W1K2231612A025399	66	W1K2231632A023342
27	W1K2231612A025762	67	W1K2231632A028809
28	W1K2231612A026424	68	W1K2231632A029078
29	W1K2231612A026967	69	W1K2231632A029094
30	W1K2231612A029746	70	W1K2231632A029235
31	W1K2231612A031978	71	W1K2231632A029823
32	W1K2231612A032268	72	W1K2231632A030738
33	W1K2231612A037087	73	W1K2231632A040084
34	W1K2231612A037335	74	W1K2231632A040165
35	W1K2231612A042594	75	W1K2231632A043445
36	W1K2231612A043135	76	W1K2231632A052575
37	W1K2231612A054314	77	W1K2231632A052921
38	W1K2231612A055739	78	W1K2231632A060538
39	W1K2231612A055935	79	W1K2231632A061548
40	W1K2231612A066463	80	W1K2231632A067423
41	W1K2231612A070453	81	W1K2231632A075837
42	W1K2231612A070867	82	W1K2231632A141063
43	W1K2231612A079867	83	W1K2239762A105553
44	W1K2231612A081026	84	W1K2239762A156089

85	W1K2239762A156714
86	W1K2239762A157598
87	W1K2239762A157943
88	W1K2239762A166262
89	W1K2239762A172280
90	W1K2239762A175871