Recall Detail				
Ref No	10001149			
Manufacturer	Rolls-Royce			
Vehicle Class	Passenger Car			
Model/Type	Ghost RR21, RR22			
Dealer (phone no)	31936999			
Subject	Instrument Cluster Glass Protective Coating Application.			
Progress	Running			
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)			
Description of Defect, how it came to light, and possible consequences if ignored.	Vehicles were manufactured with instrument cluster single-layer tempered glass that, in certain extreme high-speed side crash conditions, may break. If the glass broke into small pieces, there is a very low risk that it could increase the risk of injury.			
Remedial Action	Affected vehicles will need to receive a protective coating applied to the single-layer tempered instrument cluster glass.			
Build Dates	July 2020 – December 2022			
Launch Date	24-10-2023			
Tentative Date of Recall Completion	24-10-2024			

U205463
U216869
U207399
U207010
U209397
U205913
U207735
U203757
U212427
U203184
U207199
U207624
U210979
U209418

20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	