

Recall Detail

Ref No	10001152
Manufacturer	Mercedes-Benz AG
Vehicle Class	Passenger car
Model/Type	G-Class/ 461
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Rear axle differential drive shaft bearing (3594019)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>We have determined that the oil supply for the rear axle drive shaft bearing on certain vehicles unfortunately might not meet specifications. Under specific conditions, the bearing might overheat and lock. In consequence, the vehicle might lose its propulsion. Additionally, it cannot be completely excluded that the rear wheels lock up, which might result in a loss of controllability of the vehicle. Thus, the risk of an accident would increase. Furthermore, transmission oil might leak and/or components might separate from the vehicle, which might pose a risk for other road users.</p>
Remedial Action	As a precautionary measure, to replace the rear axle differential housing cover in the affected vehicles.
Build Dates	11/12/2009 – 15/06/2011
Launch Date	01/12/2023
Tentative Date of Recall Completion	31/12/2024

1	WDB4613332X182493
2	WDB4613332X186336

3	WDB4613332X186348
4	WDB4613332X186393

5	WDB4613332X186399
6	WDB4613332X186405
7	WDB4613332X186420
8	WDB4613332X186427
9	WDB4613332X186433
10	WDB4613332X186442
11	WDB4613332X186450
12	WDB4613332X186462
13	WDB4613332X186475
14	WDB4613332X186484
15	WDB4613332X186502
16	WDB4613332X186510
17	WDB4613332X186529
18	WDB4613332X186537
19	WDB4613332X186545
20	WDB4613332X186776
21	WDB4613332X186785
22	WDB4613332X186800
23	WDB4613332X186806
24	WDB4613332X186815
25	WDB4613332X186830
26	WDB4613332X186842
27	WDB4613332X186851
28	WDB4613332X186862
29	WDB4613332X186870
30	WDB4613332X187033
31	WDB4613332X187068
32	WDB4613332X187076
33	WDB4613332X187108
34	WDB4613332X187161
35	WDB4613332X187169
36	WDB4613332X187192
37	WDB4613332X187204
38	WDB4613332X187245
39	WDB4613332X187334
40	WDB4613332X187372
41	WDB4613332X187427
42	WDB4613332X187433
43	WDB4613332X187458
44	WDB4613332X187492

45	WDB4613332X187499
46	WDB4613332X187518
47	WDB4613332X187523
48	WDB4613332X187542
49	WDB4613332X187555
50	WDB4613332X187572
51	WDB4613332X187580
52	WDB4613332X187595
53	WDB4613332X187605
54	WDB4613332X187615
55	WDB4613332X187624
56	WDB4613332X187637
57	WDB4613332X187648
58	WDB4613332X187681
59	WDB4613332X187692
60	WDB4613332X187702
61	WDB4613332X187712
62	WDB4613332X187721
63	WDB4613332X187740
64	WDB4613332X187758
65	WDB4613332X187768
66	WDB4613332X187788
67	WDB4613332X187813
68	WDB4613332X187821
69	WDB4613332X187866
70	WDB4613332X187942
71	WDB4613332X187954
72	WDB4613332X188012
73	WDB4613332X188040
74	WDB4613332X188070
75	WDB4613332X188114
76	WDB4613332X188132
77	WDB4613332X188159
78	WDB4613332X188305
79	WDB4613332X188350
80	WDB4613332X188389
81	WDB4613332X188434
82	WDB4613332X188460
83	WDB4613332X188466
84	WDB4613332X188487

85	WDB4613332X188495
86	WDB4613332X188524
87	WDB4613332X188562
88	WDB4613332X188570
89	WDB4613332X188586
90	WDB4613332X188589
91	WDB4613332X188599
92	WDB4613332X188608
93	WDB4613332X188617
94	WDB4613332X188634
95	WDB4613332X188661
96	WDB4613332X188688
97	WDB4613332X188695
98	WDB4613332X188716
99	WDB4613332X188725
100	WDB4613332X188737
101	WDB4613332X188765
102	WDB4613332X188773
103	WDB4613332X188777
104	WDB4613332X188786
105	WDB4613332X188793
106	WDB4613332X188810
107	WDB4613332X188842
108	WDB4613332X188845
109	WDB4613332X188873
110	WDB4613332X188893
111	WDB4613332X188953
112	WDB4613332X188963
113	WDB4613332X188991
114	WDB4613332X189020
115	WDB4613332X189043
116	WDB4613332X189068
117	WDB4613332X189101
118	WDB4613332X189121
119	WDB4613332X189128
120	WDB4613332X189202
121	WDB4613332X189234
122	WDB4613332X189275
123	WDB4613332X189290
124	WDB4613332X189306

125	WDB4613332X189321
126	WDB4613332X189338
127	WDB4613332X189362
128	WDB4613332X189393
129	WDB4613332X189490
130	WDB4613332X189529
131	WDB4613332X189551
132	WDB4613332X189589
133	WDB4613332X189601
134	WDB4613332X189645
135	WDB4613332X189682
136	WDB4613332X189719
137	WDB4613332X189754
138	WDB4613332X189799
139	WDB4613332X189976
140	WDB4613332X190007
141	WDB4613332X190037
142	WDB4613332X190143
143	WDB4613332X190176
144	WDB4613332X190216
145	WDB4613332X190265
146	WDB4613332X190317
147	WDB4613332X190504
148	WDB4613332X190543
149	WDB4613332X190567
150	WDB4613332X190578
151	WDB4613332X190607
152	WDB4613332X190958
153	WDB4613332X190999
154	WDB4613332X191028
155	WDB4613332X191039
156	WDB4613332X191048
157	WDB4613332X191081
158	WDB4613332X191110
159	WDB4613332X191129
160	WDB4613332X191163
161	WDB4613332X191187
162	WDB4613332X192190

