

Recall Detail

| | |
|---|--|
| Ref No | 10001156 |
| Manufacturer | Mitsubishi Fuso Truck & Bus Corporation |
| Vehicle Class | Medium Goods Vehicle / Heavy Goods Vehicle |
| Model/Type | Fuso FP70 / FP74 / FS72 / FV70 |
| Dealer (phone no) | Universal Cars Limited (Tel: 39138818) |
| Subject | Parking brake lamp erroneously lit |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | <p>Due to water generated in the parking brake pneumatic lines leading to deterioration of the diaphragm, which is an internal component of the air switch.</p> <p>When the parking brake warning light switch failure, the parking brake lamp on the meter cluster is illuminated even though the actual parking brake lever is released.</p> |
| Remedial Action | Replace the parking brake warning light switch and change the mounting position. |
| Build Dates | From 16/05/2017 to 16/07/2021 |
| Launch Date | 29/01/2024 |
| Tentative Date of Recall Completion | 29/01/2027 |

| | |
|----|--------------|
| 1 | FP70HDA00044 |
| 2 | FP70HDA00045 |
| 3 | FP70HDA00046 |
| 4 | FP74HDA00001 |
| 5 | FP74HDA00003 |
| 6 | FP74HDA00011 |
| 7 | FP74HDA00013 |
| 8 | FP74HDA00015 |
| 9 | FP74HDA00017 |
| 10 | FP74HDA00018 |
| 11 | FP74HDA00019 |
| 12 | FP74HDA00020 |
| 13 | FP74HDA00021 |
| 14 | FP74HDA00022 |
| 15 | FP74HDA00023 |
| 16 | FP74HDA00024 |

| | |
|----|--------------|
| 17 | FP74HDA00025 |
| 18 | FP74HDA00026 |
| 19 | FP74HDA00027 |
| 20 | FS72HSA00003 |
| 21 | FS72HSA00004 |
| 22 | FS72HSA00005 |
| 23 | FS72HSA00006 |
| 24 | FS72HSA00007 |
| 25 | FS72HSA00008 |
| 26 | FS72HSA00009 |
| 27 | FS72HSA00010 |
| 28 | FS72HSA00011 |
| 29 | FS72HSA00012 |
| 30 | FS72HSA00013 |
| 31 | FS72HSA00014 |
| 32 | FS72HSA00015 |

| | |
|----|--------------|
| 33 | FS72HSA00016 |
| 34 | FS72HSA00017 |
| 35 | FS72HSA00018 |
| 36 | FS72HSA00021 |
| 37 | FS72HSA00022 |
| 38 | FS72HSA00023 |
| 39 | FS72HSA00024 |
| 40 | FS72HSA00025 |
| 41 | FS72HSA00037 |
| 42 | FS72HSA00038 |
| 43 | FS72HSA00039 |
| 44 | FV70HJA00003 |
| 45 | FV70HJA00036 |
| 46 | FV70HJA00106 |
| 47 | FV70HJA00110 |
| 48 | FV70HJA10063 |
| 49 | FV70HKA00003 |
| 50 | FV70HKA00004 |
| 51 | FV70HKA00005 |
| 52 | FV70HKA00009 |
| 53 | FV70HKA00010 |
| 54 | FV70HKA00011 |
| 55 | FV70HKA00012 |
| 56 | FV70HKA00013 |
| 57 | FV70HKA00014 |
| 58 | FV70HKA00015 |
| 59 | FV70HKA00020 |
| 60 | FV70HKA10005 |
| 61 | FV70HSA00004 |
| 62 | FV70HSA00005 |
| 63 | FV70HSA00006 |
| 64 | FV70HSA00007 |
| 65 | FV70HSA00008 |
| 66 | FV70HSA00009 |
| 67 | FV70HSA00010 |
| 68 | FV70HSA00011 |
| 69 | FV70HSA00012 |
| 70 | FV70HSA00013 |

| | |
|----|--------------|
| 71 | FV70HSA00014 |
| 72 | FV70HSA00015 |
| 73 | FV70HSA00016 |
| 74 | FV70HSA00017 |
| 75 | FV70HSA00018 |
| 76 | FV70HSA00026 |
| 77 | FV70HSA00027 |
| 78 | FV70HSA00031 |
| 79 | FV70HSA00032 |
| 80 | FV70HSA00034 |
| 81 | FV70HSA00051 |
| 82 | FV70HSA00052 |
| 83 | FV70HSA00053 |
| 84 | FV70HSA00055 |
| 85 | FV70HSA10023 |
| 86 | FV70HSA10024 |
| 87 | FV70HSA10026 |