

Recall Detail

Ref No	10001175
Manufacturer	Mercedes-Benz AG
Vehicle Class	Passenger car
Model/Type	C-Class/ 206
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Prefuse box screw connection (5497603)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	As part of this constant monitoring, we have found that the screw connection between the electric line and the prefuse box in the front passenger footwell may unfortunately have been tightened with insufficient torque in certain vehicles. As a consequence, a sudden loss of propulsion cannot be ruled out. In addition, the electric transitional resistance at this connection may increase. In consequence, the temperature in this area may increase due to the high electrical currents that can flow through this connection, which may increase the risk of thermal damage.
Remedial Action	As a precautionary measure, to check the screw connection of the prefuse box on the affected vehicles and carry out any necessary repair measures.
Build Dates	06/10/2021 – 06/07/2022
Launch Date	08/07/2024
Tentative Date of Recall Completion	30/06/2025

3	W1K2060422R010078
4	W1K2060422R010611
5	W1K2060422R010984
6	W1K2060422R011492
7	W1K2060422R011570
8	W1K2060422R015429
9	W1K2060422R030408
10	W1K2060422R030451
11	W1K2060422R053428
12	W1K2060422R054736
13	W1K2060422R054751
14	W1K2060422R055830
15	W1K2060422R062256
16	W1K2060422R064562