

Recall Detail

| | |
|---|---|
| Ref No | 10001187 |
| Manufacturer | Mercedes-Benz AG |
| Vehicle Class | Passenger car |
| Model/Type | V-Class/ 447 |
| Dealer (phone no) | Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171 |
| Subject | Fuel delivery module impeller (4790206) |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | <p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.</p> |
| Description of Defect, how it came to light, and possible consequences if ignored. | As part of this constant monitoring, we have found that the fuel delivery module in certain vehicles unfortunately might not meet specifications. In this case, the function of the fuel delivery module could be impaired under certain conditions and the fuel pump could be switched off. As a result, the vehicle could spontaneously lose propulsion. This could increase the risk of accident or injury. |
| Remedial Action | As a precautionary measure, we will replace the fuel delivery module on the affected vehicles. |
| Build Dates | 21/09/2022 – 16/01/2023 |
| Launch Date | 19/11/2024 |
| Tentative Date of Recall Completion | 31/12/2025 |

| | |
|---|-------------------|
| 1 | W1V44781324130109 |
| 2 | W1V44781324155055 |
| 3 | W1V44781324158730 |
| 4 | W1V44781524129390 |

5 W1V44781524168906