	Recall Detail				
Ref No	10001189				
Manufacturer	Mercedes-Benz AG				
Vehicle Class	Passenger Car, Light Goods Vehicle				
Model/Type	Vito, eVito, V-Class, EQV/ 447				
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171 Fanling Commercial Vehicle Service Centre: 2637 2988				
Subject	Fastening of Steering Wheel Height Adjustment (4692110)				
Progress	Running				
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. (2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Customer Service hotline (Tel: 2504 6140) to clarify whether your vehicle is affected by this recall.				
Description of Defect, how it came to light, and possible consequences if ignored.	As part of this constant monitoring, we have found that the fastening of the steering wheel height adjustment of certain vehicles might unfortunately not meet specifications. In case of a frontal crash, the fastening of the steering wheel height adjustment might not withstand the forces. As a result, increased occupant loads and therefore, an increased risk of injury cannot be ruled out for the driver.				
Remedial Action	As a precautionary measure, we will replace the steering column tube on the affected vehicles.				
Build Dates	01/03/2024 — 09/03/2024				
Launch Date	22/11/2024				
Tentative Date of Recall Completion	31/12/2025				

1	W1V44770324374641
2	W1V44770324387270
3	W1V44770524372331

4	W1V44770524374792
5	W1V44781524374741