

Recall Detail	
Ref No	<b>10001202</b>
Manufacturer	MINI (Diesel)
Vehicle Class	Passenger Car
Model/Type	Cooper S series (F56) with B47O engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936699)
Subject	Replacing exhaust-gas recirculation cooler (0011240700)
Progress	<b>Running</b>
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The exhaust gas recirculation coolers can possibly leak over the service life of the vehicle.</p> <p>In the worst case, the exhaust gas recirculation cooler can leak. The escaping coolant could create flammable deposits combined with the soot and oil deposits in the exhaust-gas recirculation cooler. In rare cases, this could lead to local scorching on the intake system and, in extreme cases, a thermal incident can occur.</p>
Remedial Action	Replace exhaust-gas recirculation cooler
Build Dates	14/05/2015 – 15/02/2016
Launch Date	21/4/2023
Tentative Date of Recall Completion	31/12/2025

1	WMWXN92070T736513
2	WMWXN92080T736519
3	WMWXN92060T736518
4	WMWXN92040T736517
5	WMWXN92050T736543
6	WMWXN92010T736541
7	WMWXN92090T736531
8	WMWXN92090T736545
9	WMWXN92000T736515
10	WMWXN92050T736526
11	WMWXN920002D25558

12	WMWXN92000T736546
13	WMWXN92090T736514
14	WMWXN92020T736516
15	WMWXN92030T736525
16	WMWXN92040T736520