

Recall Detail

Ref No	10001203
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Medium Goods Vehicle / Heavy Goods Vehicle
Model/Type	Fuso FP51 / FK62
Dealer (phone no)	Universal Cars Limited (Tel: 39138913 Service Center Hotline)
Subject	Combination switch internal failure
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to combination switch internal failure, turn signal lights don't work even the lever of the combination switch operated.
Remedial Action	Inspection or replace combination switch.
Build Dates	From 02/06/2017 to 03/09/2019
Launch Date	12/05/2025
Tentative Date of Recall Completion	12/05/2028

FK62FGA20037
 FK62FGA20038
 FK62FGA20039
 FK62FGA20040
 FK62FGA20041
 FK62FGA20042
 FK62FGA20043
 FK62FGA20044
 FK62FGA20045
 FK62FGA20046
 FK62FGA20047
 FK62FGA20049
 FK62FGA20050
 FK62FGA20051
 FK62FGA20052
 FK62FGA20054
 FK62FGA20055
 FK62FGA20056
 FK62FGA20057

FK62FGA20058
 FK62FGA20061
 FK62FKA20036
 FK62FKA20037
 FK62FKA20038
 FK62FKA20039
 FK62FKA20040
 FK62FKA20041
 FK62FKA20042
 FK62FKA20043
 FK62FKA20044
 FK62FKA20045
 FK62FKA20046
 FK62FKA20047
 FK62FKA20049
 FK62FKA20050
 FK62FKA20051
 FK62FKA20052
 FK62FKA20053

FK62FKA20054

FP51SDA20281

FP51SDA20282