

## Recall Detail

<b>Ref No</b>	<b>10001210</b>
<b>Manufacturer</b>	Mitsubishi Fuso Truck & Bus Corporation
<b>Vehicle Class</b>	Light Goods Vehicle / Medium Goods Vehicle / Light Bus / Bus
<b>Model/Type</b>	Fuso FEB / FEC / BE7
<b>Dealer (phone no)</b>	Universal Cars Limited (Tel: 39138913 Service Center Hotline)
<b>Subject</b>	Single Signal detect and Actuation Module (SSAM) Malfunction
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to SSAM software failure may make SSAM no response. As a result, the engine may not be start.
<b>Remedial Action</b>	Update SSAM software.
<b>Build Dates</b>	From 20/06/2024 to 23/12/2024
<b>Launch Date</b>	16/06/2025
<b>Tentative Date of Recall Completion</b>	16/06/2028

BE741GM10269  
 BE741GM10270  
 BE741GM10271  
 BE741GM10272  
 BE741GM10273  
 BE741GM10274  
 BE741GM10276  
 BE741GM10277  
 BE741GM10278  
 BE741GM10279  
 BE741GM10280  
 BE741GM10281  
 BE741GM10282  
 BE741GM10283  
 BE741GM10284  
 BE741GM10285  
 BE741GM10286  
 BE741GM10287  
 BE741GM10288

BE741GM10289  
 BE741GM10290  
 BE741GM10291  
 BE741GM10292  
 BE741GM10302  
 BE741GM10306  
 BE741GM10307  
 BE741GM10308  
 BE741GM10319  
 BE741GM10320  
 BE741JM11121  
 FEB71EA35326  
 FEC71GA35080  
 FECX1HA35149  
 FECX1HA35150