

Recall Detail

Ref No	10001219
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Light Goods Vehicle / Medium Goods Vehicle
Model/Type	Fuso eCanter
Dealer (phone no)	Universal Cars Limited (Tel: 39138913 Service Center Hotline)
Subject	ePB Dragging
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to the spacer of the ePB actuator too large, it may cause the system overcurrent. The parking brake may stop when engaging or releasing the brake before completing operation. When this issue occurs, ePB warning lamp in the meter cluster will light up. If driver does not notice the warning and continues driving, the brake may partially engaged causing overheat.
Remedial Action	Check the brake ASM and replace ePB actuator.
Build Dates	From 01/11/2024 to 12/03/2025
Launch Date	29/09/2025
Tentative Date of Recall Completion	29/09/2028

FEC6KEA00001
FEC6KGA00001
FECXKGA00002
FECXKHA00002
FECXKHA00005
FECXKHA00006
FECXKHA00007
FECXKHA00008