

Recall Detail	
Ref No	10001225
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Supra
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Replace starter (TN8)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	In some cases, water could contact the starter's electrical relay and, over time, lead to corrosion. Corrosion inside the starter relay could affect the electrical connection within the relay and ability to start the engine. In certain cases, corrosion inside the starter relay could also lead to a short-circuit and possible overheating of the starter.
Remedial Action	Replace starter
Build Dates	February 2019 to June 2019
Launch Date	13 November 2025
Tentative Date of Recall Completion	31 December 2027

- 1 WZ1DB22000W022616
- 2 WZ1DB22010W021202
- 3 WZ1DB22070W022385
- 4 WZ1DB220X0W021084