

Takata Airbag Recall Detail [Applicable for domestic models not imported through authorized dealers]	
Manufacturer	Mazda Motor Corporation
Vehicle Class	Private car
Models/Type	Mazda6 (GJ8S, GK3F, GM9N, GM9R, GM9S, GS0M, GS0P, GS0S, GS1B), RX-8 (FE32), E-Series (SJ92)
Manufacturing Years	April 2002 to November 2007 (Mazda 6) August 2003 to October 2007 (RX-8) March 2004 to March 2006 (E-Series)
Dealer Contact Person: Contact Number:	Vang Iek Motors (Hong Kong) Limited Service Department 37684848
Remedial Action	Replace the driver side and/or passenger side inflator with good one
Tentative Date of Recall Completion	31/10/2018

高田安全氣袋召回詳情 [適用於本地平行進口或個別進口之型號]	
製造商	萬事得
車輛類別	私家車
型號	Mazda6 (GJ8S, GK3F, GM9N, GM9R, GM9S, GS0M, GS0P, GS0S, GS1B), RX-8 (FE32), E-Series (SJ92)
製造年份	2002年4月至2007年11月 (Mazda6) 2003年8月至2007年10月 (RX-8) 2004年3月至2006年3月 (E-Series)
代理商 聯絡人: 聯絡電話:	宏益汽車(香港)有限公司 服務中心 37684848
修正行動	更換司機和/或乘客前安全氣囊充氣部件
估計回收行動的完成日期	31/10/2018