

Recall Detail

Ref No	10000143
Manufacturer	Toyota
Vehicle Class	Light Bus / Bus
Model/Type	Coaster
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Steering knuckle replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Crack might occur on the steering knuckle
Remedial Action	Replace the steering knuckle & related parts
Build Dates	January 2003 ~ March 2004
Launch Date	September 2004
Tentative Date of Recall Completion	December 2013

1	BB42-0001066
2	BB42-0001092
3	BB42-0001706
4	BB42-0002309
5	BB42-0002369
6	BB42-0002562
7	BB42-0002605
8	BB42-0002633
9	BB42-0003097
10	HZB50-0001253
11	HZB50-0001277
12	HZB50-0002371
13	HZB50-0003384
14	HZB50-0003845
15	JT743BB4207000012
16	JT743BB4207000513
17	JT743BB4207000684
18	JT743BB4207000699
19	JT743BB4207001286
20	JT743BB4207001499

21	JT743BB4207001520
22	JT743BB5008000027
23	JT743BB5008000221
24	JT743BB5008000403
25	JT743PB5108000930
26	JT743PB5108001507
27	JT743PB5108001897
28	JT743PB5108002999
29	JT743PB5108003027
30	JT743PB5108003080
31	JT743PB5108003115
32	JTGFG518X07000136
33	JTGFG518X04000083
34	JTGFG418302000184