

Recall Detail

Ref No	10000194
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Prius
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Steering intermediate shaft replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	There is a possibility that a crack would be developed at the sleeve of the steering intermediate shaft if the vehicle is operated under certain operating conditions where a large force is repeatedly applied to the connection (e.g. when the tire contacts roadside curbs while driving).
Remedial Action	Replace the steering intermediate shaft
Build Dates	July 2003 ~ November 2005
Launch Date	June 2006
Tentative Date of Recall Completion	December 2012

1	JTDKB22U100034107
2	JTDKB22U103075996
3	JTDKB22U200104620
4	JTDKB22U603031038
5	JTDKB22U603054755
6	JTDKB22U800034508
7	JTDKB22UX03025954