

Recall Detail	
Ref No	10000265
Manufacturer	Ford
Vehicle Class	M1 – Private Car
Model/Type	Explorer
Dealer (phone no. / e-mail)	Future Motors Limited - (Tel: 28205151 / <a href="mailto:fordservice@futuremotors.com.hk">fordservice@futuremotors.com.hk</a> )
Subject	Speed control system modification
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The underhood speed control deactivation switch may overheat, smoke, or burn, which could result in an underhood fire.
Remedial Action	To inspect and modify the speed control switch harness connector.
Build Dates	1998 to 2002
Launch Date	18 May 2008
Tentative Date of Recall Completion	31 December 2015

1	1LNLM81W2SY740278
2	1FMZU34E3WZA35487
3	1FMZU34E1WZA72876
4	1FMZU34E9WZA84337
5	1FMZU34X0WZA84860
6	1FMZU34E8WZA84863
7	1FMZU34E1WZA35486
8	1LNLM82W2VY702424
9	1LNLM82W7VY691498
10	1FMZU34E4WZA84861
11	1FMZU34E6WZA84862