

## Recall Detail

<b>Ref No</b>	<b>10000311</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	LS460 / LS460L / LS600hL
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	Steering Control ECU
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The steering wheel may over-rotate when the driver returns it to the centre position after turning it sharply to the left or right for several seconds, whereas the car remains moving straight ahead.
<b>Remedial Action</b>	Replace the steering control ECU
<b>Build Dates</b>	September 2009 ~ May 2010
<b>Launch Date</b>	June 2010
<b>Tentative Date of Recall Completion</b>	December 2012

1	JTHBL46F405044734
2	JTHGL46F305003520
3	JTHDU46F305010855
4	JTHDU46FX05010898
5	JTHGL46F405038213
6	JTHGL46F205038243
7	JTHGL46F905039230