

Recall Detail

Ref No	10000315
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	LS460 / LS460L / LS600hL
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Engine valve springs replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Existence of impurities during the production of valve spring. Hence, the durability of valve spring will be decreased and the output of the vehicle may be affected.
Remedial Action	Replace the engine valve springs.
Build Dates	August 2005 ~ September 2008
Launch Date	19 July 2010
Tentative Date of Recall Completion	December 2018

1	JTHDU46F305007244
2	JTHDU46F505001400
3	JTHDU46F705006114
4	JTHDU46FX05006186
5	JTHBL46F105083474
6	JTHBL46F405035144
7	JTHBL46F505079945
8	JTHBL46F705014076
9	JTHGL46F005000655
10	JTHGL46F005004558
11	JTHGL46F105002818
12	JTHGL46F105002849
13	JTHGL46F105003855
14	JTHGL46F105003984
15	JTHGL46F105022065
16	JTHGL46F205002052
17	JTHGL46F205002990
18	JTHGL46F205011916
19	JTHGL46F205021328
20	JTHGL46F305003159
21	JTHGL46F305006580
22	JTHGL46F305007325
23	JTHGL46F405000979
24	JTHGL46F405004840
25	JTHGL46F405008970
26	JTHGL46F405012047

27	JTHGL46F405018849
28	JTHGL46F405023131
29	JTHGL46F405023369
30	JTHGL46F405028877
31	JTHGL46F505002594
32	JTHGL46F505020500
33	JTHGL46F505023008
34	JTHGL46F605002233
35	JTHGL46F605002376
36	JTHGL46F605012115
37	JTHGL46F705015539
38	JTHGL46F805004680
39	JTHGL46F805021253
40	JTHGL46F805022113
41	JTHGL46F905002176
42	JTHGL46F905002260
43	JTHGL46F905003294
44	JTHGL46F905004719
45	JTHGL46F905007054
46	JTHGL46F905012318
47	JTHGL46F905020368
48	JTHGL46FX05002879
49	JTHGL46FX05009637
50	JTHGL46FX05012182