

<b>Recall Detail</b>	
<b>Ref No</b>	<b>10000317</b>
<b>Manufacturer</b>	Suzuki Motor Corporation
<b>Vehicle Class</b>	Light Truck
<b>Model/Type</b>	Every DA64V
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Replacement of improved generator harness set.
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The wire-harness being press fit with generator terminal could have a possibility to be corroded. In the worst case, engine will finally be stopped and will not be restarted.
<b>Remedial Action</b>	Replacement of improved generator harness set.
<b>Build Dates</b>	From 2005 to 2007
<b>Launch Date</b>	02/09/2010
<b>Tentative Date of Recall Completion</b>	31/12/2011

1	<b>DA64V-131285</b>
2	<b>DA64V-131479</b>
3	<b>DA64V-131140</b>
4	<b>DA64V-134643</b>
5	<b>DA64V-135257</b>
6	<b>DA64V-135558</b>
7	<b>DA64V-135973</b>
8	<b>DA64V-136324</b>
9	<b>DA64V-138503</b>
10	<b>DA64V-138791</b>
11	<b>DA64V-139211</b>
12	<b>DA64V-139405</b>
13	<b>DA64V-139465</b>
14	<b>DA64V-139519</b>
15	<b>DA64V-140592</b>
16	<b>DA64V-141113</b>
17	<b>DA64V-141531</b>
18	<b>DA64V-143919</b>
19	<b>DA64V-150127</b>
20	<b>DA64V-150255</b>

21	<b>DA64V-154564</b>
22	<b>DA64V-154956</b>
23	<b>DA64V-155445</b>
24	<b>DA64V-155729</b>
25	<b>DA64V-156294</b>
26	<b>DA64V-160023</b>
27	<b>DA64V-160489</b>
28	<b>DA64V-160738</b>
29	<b>DA64V-160739</b>
30	<b>DA64V-161128</b>
31	<b>DA64V-161237</b>
32	<b>DA64V-161582</b>
33	<b>DA64V-161854</b>
34	<b>DA64V-161863</b>
35	<b>DA64V-161957</b>
36	<b>DA64V-165096</b>
37	<b>DA64V-165501</b>
38	<b>DA64V-165843</b>
39	<b>DA64V-165909</b>
40	<b>DA64V-166147</b>

41	<b>DA64V-166652</b>
42	<b>DA64V-166800</b>
43	<b>DA64V-167182</b>
44	<b>DA64V-168625</b>
45	<b>DA64V-168844</b>
46	<b>DA64V-168847</b>
47	<b>DA64V-169088</b>
48	<b>DA64V-169419</b>
49	<b>DA64V-169418</b>
50	<b>DA64V-169640</b>
51	<b>DA64V-170019</b>
52	<b>DA64V-170227</b>
53	<b>DA64V-170475</b>
54	<b>DA64V-171637</b>
55	<b>DA64V-171838</b>
56	<b>DA64V-172056</b>
57	<b>DA64V-179781</b>
58	<b>DA64V-180098</b>
59	<b>DA64V-180440</b>
60	<b>DA64V-180735</b>
61	<b>DA64V-181046</b>
62	<b>DA64V-181293</b>
63	<b>DA64V-181603</b>
64	<b>DA64V-183990</b>
65	<b>DA64V-186318</b>
66	<b>DA64V-186427</b>
67	<b>DA64V-186983</b>
68	<b>DA64V-188712</b>
69	<b>DA64V-189750</b>
70	<b>DA64V-189918</b>
71	<b>DA64V-190145</b>
72	<b>DA64V-190436</b>
73	<b>DA64V-190514</b>
74	<b>DA64V-190717</b>
75	<b>DA64V-190979</b>
76	<b>DA64V-191149</b>
77	<b>DA64V-191366</b>
78	<b>DA64V-191547</b>
79	<b>DA64V-191685</b>
80	<b>DA64V-191873</b>

81	<b>DA64V-192052</b>
82	<b>DA64V-192419</b>
83	<b>DA64V-192429</b>
84	<b>DA64V-192825</b>
85	<b>DA64V-193004</b>
86	<b>DA64V-193168</b>
87	<b>DA64V-193975</b>
88	<b>DA64V-194317</b>
89	<b>DA64V-194864</b>
90	<b>DA64V-195032</b>
91	<b>DA64V-195217</b>
92	<b>DA64V-195772</b>
93	<b>DA64V-195987</b>
94	<b>DA64V-196170</b>
95	<b>DA64V-196469</b>
96	<b>DA64V-196730</b>
97	<b>DA64V-197074</b>
98	<b>DA64V-197260</b>
99	<b>DA64V-197532</b>
100	<b>DA64V-197858</b>
101	<b>DA64V-198084</b>
102	<b>DA64V-198600</b>
103	<b>DA64V-198725</b>
104	<b>DA64V-199183</b>
105	<b>DA64V-199491</b>
106	<b>DA64V-200210</b>
107	<b>DA64V-200587</b>
108	<b>DA64V-201481</b>
109	<b>DA64V-202513</b>
110	<b>DA64V-203152</b>
111	<b>DA64V-204997</b>
112	<b>DA64V-205555</b>
113	<b>DA64V-250225</b>
114	<b>DA64V-250446</b>
115	<b>DA64V-250079</b>
116	<b>DA64V-252526</b>
117	<b>DA64V-253113</b>
118	<b>DA64V-253344</b>
119	<b>DA64V-253578</b>
120	<b>DA64V-253712</b>

121	<b>DA64V-253797</b>
122	<b>DA64V-254168</b>
123	<b>DA64V-254326</b>
124	<b>DA64V-254506</b>
125	<b>DA64V-254839</b>
126	<b>DA64V-255003</b>
127	<b>DA64V-257780</b>
128	<b>DA64V-257873</b>
129	<b>DA64V-258491</b>
130	<b>DA64V-258998</b>
131	<b>DA64V-259126</b>
132	<b>DA64V-259394</b>
133	<b>DA64V-260006</b>
134	<b>DA64V-260383</b>
135	<b>DA64V-261343</b>
136	<b>DA64V-261999</b>
137	<b>DA64V-262581</b>
138	<b>DA64V-263184</b>
139	<b>DA64V-263758</b>
140	<b>DA64V-264022</b>
141	<b>DA64V-264680</b>