

Recall Detail

Ref No	10000369
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Alphard 3.0/Camry 3.0
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Crankshaft pulley inspection/replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Inadequate amount of adhesive agent applied between the outer ring and the torsional rubber damper (inner ring) in the crankshaft pulley, causing a possibility that the outer ring may become misaligned which can cause abnormal engine vibration. In some cases, the belt for the power steering pump may become detached from the pulley which could affect the power assist of the steering.
Remedial Action	Inspect or replace the crankshaft pulley
Build Dates	June 2004 ~ March 2005
Launch Date	9 November 2011
Tentative Date of Recall Completion	December 2018

1	JT711MP1000053628
2	JT711MP1000053635
3	JT711MP1000053686
4	JT711MP1000053687
5	JT711MP1000053702
6	JT711MP1000053897
7	JT711MP1000053905
8	JT711MP1000053993
9	JT711MP1000054081
10	JT711MP1000054283
11	JT711MP1000054372
12	JT711MP1000054463
13	JT711MP1000054493
14	JT711MP1000054591
15	JT711MP1000054615
16	JT711MP1000054784
17	JT711MP1000054806
18	JT711MP1000054967
19	JT711MP1000055485
20	JT711MP1000055537
21	JT711MP1000055564

22	JT711MP1000055574
23	JT711MP1000055634
24	JT711MP1000055682
25	JT711MP1000055752
26	JT711MP1000055882
27	JT711MP1000055883
28	JT711MP1000056055
29	JT711MP1000056059
30	JT711MP1000056165
31	JT711MP1000056286
32	JT711MP1000056472
33	JT711MP1000056536
34	JT711MP1000056547
35	JT711MP1000056779
36	JT711MP1000056918
37	JT711MP1000057060
38	JT711MP1000057378
39	JT711MP1000057398
40	JT711MP1000058020
41	JT711MP1000058050
42	JT711MP1000058283

43	JT711MP1000058764
44	JT711MP1000058863
45	JT711MP1000059059
46	JT711MP1000059474
47	JT711MP1000059665
48	JT711MP1000059762
49	JT711MP1000059871
50	JT711MP1000059949
51	JT711MP1000060092
52	JT711MP1000060154
53	JT711MP1000060183
54	JT711MP1000060246
55	JT711MP1000060271
56	JT711MP1000060355
57	JT711MP1000060451
58	JT711MP1000060468
59	JT711MP1000060515
60	JT711MP1000060547
61	JT711MP1000060557
62	JT711MP1000060655
63	JT711MP1000060840
64	JT711MP1000060949
65	JT711MP1000061003
66	JT711MP1000061084
67	JT711MP1000061177
68	JT711MP1000061260
69	JT711MP1000061352
70	JT711MP1000061622
71	JT711MP1000061810
72	JT711MP1000061816
73	JT711MP1000062080
74	JT711MP1000062149
75	JT711MP1000062338
76	JT711MP1000062493
77	JT711MP1000062495
78	JT711MP1000062769
79	JT711MP1000062842
80	JT711MP1000062957
81	JT711MP1000063143
82	JT711MP1000063485
83	JT711MP1000063586

84	JT711MP1000063645
85	JT711MP1000063738
86	JT711MP1000063814
87	JT711MP1000063990
88	JT711MP1000064098
89	JT711MP1000064164
90	JT711MP1000064470
91	JT711MP1000064483
92	JT711MP1000064565
93	JT711MP1000064636
94	JT711MP1000064820
95	JT711MP1000064827
96	JT711MP1000065531
97	JT711MP1000066717
98	JT711MP1000067031
99	JT711MP1000067132
100	JT711MP1000067210
101	JT711MP1000067324
102	JT711MP1000067334
103	JT711MP1000067513
104	JT711MP1000067888
105	JT711MP1000068163
106	JT711MP1000068176
107	JT711MP1000068270
108	JT711MP1000068342
109	JT711MP1000068429
110	JT711MP1000068493
111	JT711MP1000068597
112	JT711MP1000068985
113	JT711MP1000069196
114	JT711MP1000069269
115	JT711MP1000070242
116	JT711MP1000070333
117	JT711MP1000070768
118	JT711MP1000070882
119	JTDBF30K000158445
120	JTDBF30K100158776
121	JTDBF30K400159078
122	JTDBF30K500158540
123	JTDBF30K600159101