

## Recall Detail

<b>Ref No</b>	<b>10000475</b>
<b>Manufacturer</b>	Lamborghini
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Gallardo
<b>Dealer (phone no)</b>	29292919
<b>Subject</b>	Carbon Ceramic Brake Fasteners Replacement
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The stainless steel screws fixing the rotor to the metal bell may fail due to stress corrosion cracking,if the vehicle has been used in extreme salt environments.
<b>Remedial Action</b>	Check the stainless steel screws and replace it if out of standard.
<b>Build Dates</b>	Model Year 2007 – 2009 (VIN: LA04413 – LA08928)
<b>Launch Date</b>	April, 2014
<b>Tentative Date of Recall Completion</b>	December, 2014

1	ZHWGE22TX7LA05132
2	ZHWGE43T68LA05446
3	ZHWGE43T98LA05621
4	ZHWGE43T08LA05765
5	ZHWGE43TX8LA06325
6	ZHWGE43T18LA06598
7	ZHWGE43T08LA06818
8	ZHWGE43T78LA06850
9	ZHWGE43T18LA06925
10	ZHWGE54T69LA07347
11	ZHWGE54T19LA08566
12	
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	