

Recall Detail

Ref No	10000476
Manufacturer	Lamborghini
Vehicle Class	Private Car
Model/Type	Murcielago
Dealer (phone no)	29292919
Subject	Carbon Ceramic Brake Fasteners Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The stainless steel screws fixing the rotor to the metal bell may fail due to stress corrosion cracking,if the vehicle has been used in extreme salt environments.
Remedial Action	Check the stainless steel screws and replace it if out of standard.
Build Dates	Model Year 2006 – 2010 (VIN: LA01713 – LA04099)
Launch Date	April, 2014
Tentative Date of Recall Completion	December, 2014

1	ZHWBE37S07LA02374
2	ZHWBE37S07LA02393
3	ZHWBE37S08LA02839
4	ZHWBE37S08LA02767
5	ZHWBE37S08LA03143
6	ZHWBE47S09LA03417
7	ZHWBE37S09LA03518
8	ZHWBE37SX9LA03691
9	ZHWBE81H1ALA03903
10	ZHWBE81H1ALA03920
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	